



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 FORD FOCUS

TREND | 108,263 KM

VIN: WF0BC3KB9GLJ80326

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort








Power driver seat


Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 108263 |  Specs | Yes |
|  Engine | 1.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | HATCHBACK |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Blue |
|  Interior Trim | Fabric Trim |  Number of Airbags | 4 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WF0BC3KB9GLJ80326 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | |
|--|---|--|
|  Comfort & Convenience | | |
| Climate Control AC  | Steering Mounted Audio Controls  | |
|  Exteriors | | |
| Fog Light Front  | Halogen Headlights  | |
|  Safety & Security | | |

| | | | |
|--|---|----------------------|---|
| Parking Sensors Rear | ✓ | Traction Control | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Handle: Scratch < 50mm



Front right door
Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door
Handle: Scratch < 50mm



Rear right door
Handle: Scratch < 50mm



Fenders Condition

Left Fender
Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm



Right Fender
Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel
Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Right Quarter Panel
Glass: Beading Fair Use Wear/Disfiguration < 100mm, Light Scuffing < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper
Rear Bumper: Dent < 50mm, Light Scuffing < 80mm



Hood Condition

Hood
Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Trunk Condition

Trunk




Trunk condition

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber Beading Fair Use Wear 

Pillars Condition

Left A Pillar  Right A Pillar 

Left A to B Pillar Beading  Right A to B Pillar Beading 

Right A to B Pillar  Left B Pillar 

Left B Pillar Trim  Left B to C Pillar Beading 

Right C Pillar Trim  Right B to C Pillar 

Right B to C Pillar Beading  Left C Pillar 

Running Board Condition

Left Running Board Condition: Scratch < 80mm  Right Running Board Condition: Light Scuffing < 80mm 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm  Rear Windshield 

Structural Assessment

Chassis Condition  Radiator Support 

Apron  Boot Floor 

Firewall Condition  Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror  Left Side Mirror 

Right Side Mirror  Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm  Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm 

| | | | |
|--|---|-----------------------|---|
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition Light Scuffing < 50mm | ⚠ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition Rear Trunk Panel Dent < 30mm | ⚠ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |

Pedals 

Suspension

Shock Absorbers 

 **Electricals, Controls & Lights**

Keys

Master Key 

Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Sunroof Operation

Sunroof 

Lights

Headlight
Right: Light Scuff Marks < 50mm 

Interior Lights 

Tail Light Cluster 

Turn Signal Lights 

License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling 

AC Switch
Button(s) Faded 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Parking Sensors 

Rear Defogger 

Not Working

USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Trim: Light Scuffing/Disfiguration



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner

Front Left: Crack/Fair Use Wear



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<75%

RHS Rear Tyre

<65%

Spare Tyre

No spare
tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE