



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN ALTIMA**

**S | 27,504 KM**

VIN: 1N4BL4A93LC230578

## Car highlights



### **Low Mileage**

This car has been driven less than 15,000 km  
a year



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat












## Basic Details

 Kilometers	<b>27504</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>1N4BL4A93LC230578</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Automatic Headlights	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	

Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Entertainment</b>			
Bluetooth Player		USB Charging Port	
USB player			
 <b>Exteriors</b>			
Halogen Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Rear left door



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



Rear Bumper: Chip < 8mm

### Hood Condition

Hood



### Trunk Condition

Trunk



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Low Visual Dent < 30mm	!
Running Board Condition			
Left Running Board	!	Right Running Board	✓
Front Left Sill Trim: Minor Scuffing < 80mm			
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Light Scuffing < 50mm			
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

### **Steering, Suspension & Brakes**

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			
Shock Absorbers	✓		

### **Electricals, Controls & Lights**

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	⚠
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	⚠	Grab Handle	✓
Carpet	✓	Headliner	✓



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE