



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2015 MERCEDES BENZ C 200 STD | 130,583 KM

VIN: WDDWF4CB1FR000161

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat


Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B to C Pillar Beading	✓	Right B to C Pillar	✓
-		Left C Pillar	
Right B to C Pillar Beading	•	Lett G Pillar	
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear <	(!)	Rear Windshield	✓
50mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	~
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	~
Head Light Support Condition	✓		
Cowl Top			
Cowl Top			
Fair Use Wear/Crack<5mm	(!)		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	~
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	(!)	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	!
Scuff < 80mm		Scuff < 80mm	
		Right Rear Alloy/ Rim	
Right Front Alloy/ Rim	~	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/	(!)
		Scuff < 80mm	
Wheel Arch	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panal Condition			

Panel Condition

Rear Trunk Panel	✓		
Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	~
Turbocharger/ Supercharger	✓	Radiator Coolant	~
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	~
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	~
Brake Disc & Brake Pad	✓	Brake Fluid	~
Pedals	✓		
Suspension			
Shock Absorbers	✓		
Floatricola Controla Children			
Electricals, Controls & Lights			
Keys Meeter Key		Spara Kov(a)	
Master Key	•	Spare Key(s)	•
Door Locks			
Child Safety Locking	✓		

Dashboard				
Instrument Panel				
Malfunction Indication Lights: Engine	!			
Temperature Warning Light				
Airbags				
Airbags	✓			
Controls	~	Cruise Control	✓	
Infotainment Display	✓	Engine Sensors	✓	
OBD Connector	✓	Music System Audio Inputs: Connectivity Issue	!	
		Addio iliputs. Collifectivity issue		
Lights				
Headlight	~	Interior Lights	✓	
Tail Light Cluster		Daylight Running Lights		
rail Light Gluster		Daylight Running Lights	•	
License Plate Light	✓			
Air Conditioning				
AC Cooling	~	AC Switch	✓	
AC System Leaks	✓	Center AC Vent	•	
Front Right AC Vent	✓	Heater	✓	
Parking Sensors	(!)	Rear Defogger		
Front Sensors: Not Working/ Faulty		Real Deloggel		
USB Charging Port	✓	Power/ Manual Windows		
☐ Interiors & Luggage				
interiors & Luggage				
Dashboard And Instrument Panel	✓	Central Console	✓	
Cup Holder	✓	Glove Box	✓	
Steering Wheel				
Color Faded	!	Sunvisor	✓	
Seat Upholstery	~	Manual Seat Movement	✓	

Seat Belts	✓	Head Rest	•
Door Controls And Trim	✓	Grab Handle	•
Carpet	✓	Headliner Front Left: Headliner Loose	(!)
Rear View Mirror	•	Toolkit	•
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	No spare		
	tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE