



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 HYUNDAI TUCSON**

**GL | 144,006 KM**

VIN: KMHJT81E2FU962687

## **Car highlights**



### **Bluetooth**

Enjoy your drive with bluetooth



### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**
















Power driver seat



### **Airbag safety**










Airbag Driver Front

Basic Details

 Kilometers	144006	 Specs	Yes
 Engine	2.0L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KMHJT81E2FU962687		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 Comfort & Convenience			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Central Armrest			



## Entertainment

Bluetooth Player



USB player



## Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 


## Exterior

### Doors condition

#### Front left door

Weather Strip: Minor Rubber Fair Use Wear 


#### Front right door

Panel: Scuffing > 50mm, Low Visibility Dent <   
30mm, Paint Chip-off < 5mm

#### Rear left door

Handle: Paint Chip-off < 5mm 

#### Rear right door

Panel: Fully Repainted, Scuffing > 50mm,   
Low Visual Dent < 30mm

### Fenders Condition

#### Left Fender

Fender Liner: Crack/ Fair Use Wear 

#### Right Fender

Condition: Scuffing > 50mm, Low Visual Dent   
< 30mm, Partially Repainted, Paint Chip-off < 5mm

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Light Scuffing<50mm 

#### Right Quarter Panel

Condition: Low Visual Dent < 30mm 


### Front Bumper Condition

#### Front Bumper

Condition: Fair Use Wear 

### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Crack/ Misaligned, Light   
Scuffing < 80mm

### Hood Condition

#### Hood

Bonnet: Light Scuffing < 50mm 

### Trunk Condition

#### Trunk



#### Trunk conditon

#### Trunk



### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar Condition: Light Scuffing Scratch < 50mm	!
Left B Pillar Trim Light Scuffing	!	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading Beading Crack/ Tear > 5mm	!	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Light Scuffing < 80mm	!	Right Running Board Front Right Sill Trim: Low Visual Dent < 50mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Scuffing > 50mm	!
Monogram	✓	Window Glass	✓
Wiper Operation: Cover Missing	!		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key

Button Faded



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System

Condition: Button(s) Faded



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster

Right Tail Lamp: Colour Low Brightness



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent  
Crack/Fair Use Wear



Front Right AC Vent



Heater



Rear Blower Switch



USB Charging Port



Power/ Manual Windows







## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Box: Minor Disfiguration, Minor Crack/Fair Use Wear/ Scuffing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	!	Grab Handle	✓
Carpet Front Left Floor Carpet: Smudge/Fair Use Wear	!	Headliner Front Left: Light Smudge/Disfiguration, Light Scuffing	!
Rear View Mirror	✓	Toolkit	✓



## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE