



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2015 FORD FOCUS**

**AMBIENTE | 159,184 KM**

**VIN: WF0BC2KF3FLG71618**

## **Car highlights**



### **Music System**

Enjoy your drive with music system



### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**

Power driver seat



### **Airbag safety**

Airbag Driver Front

## Basic Details

 Kilometers	<b>159184</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>HATCHBACK</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WF0BC2KF3FLG71618</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Rear Bumper Spoiler		Halogen Headlights	
 Safety & Security			
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			



### Comfort & Convenience

Steering Mounted Audio  
Controls



Rear Defogger



### Entertainment

Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Right Fender: Dent < 30mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Glass: Beading Fair Use Wear/Disfiguration > 100mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint



Chip-off < 5mm

Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	
		Door Skirting: Colour Mismatch/ Fade/ Fair	!
		Use Wear	
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		

## Panel Condition

Rear Trunk Panel



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking 

Dashboard 

Instrument Panel 

Airbags 

Airbags 

Controls 

Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Lights 

Headlight 

Left: Light Scuff Marks < 50mm 

Interior Lights 

Tail Light Cluster 

License Plate Light 

Air Conditioning 

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

USB Charging Port 

Power/ Manual Windows 

## **Interiors & Luggage**

Dashboard And Instrument Panel 

Dashboard Trim: Light Scuffing/Disfigurement 

Central Console 

Glove Box 

Steering Wheel 

Sunvisor 

Seat Upholstery 

Manual Seat Movement 

Seat Belts 

Head Rest 

Door Controls And Trim 

Grab Handle 

Carpet 

Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<55%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE