



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 JEEP GRAND CHEROKEE

LIMITED | 65,389 KM

VIN: 1C4RJFBG8KC679390

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort









Power driver seat, Memory Seats








Basic Details

 Kilometers	65389	 Specs	Yes
 Engine	3.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1C4RJFBG8KC679390		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
 Exteriors			
Fog Light Front			
 Safety & Security			

Parking Sensors Front		Navigation	
Parking Sensors Rear		Reverse Camera	
 Entertainment			
USB Charging Port		Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Handle: Scratch < 50mm



Front right door
Handle: Light Scuffing < 50mm



Rear left door
Handle: Scratch < 50mm



Rear right door
Handle: Scratch < 50mm



Fenders Condition

Left Fender
Condition: Scratch < 50mm



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel
Condition: Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board Condition: Low Visual Dent < 50mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Condition: Air Bubbles	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓

Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Battery

Battery Terminal & Tightness	✓		
------------------------------	---	--	--

Fuel System

Fuel Cap	✓	Fuel Tank	✓
----------	---	-----------	---

Transmission Operation

Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering

Steering wheel	✓		
----------------	---	--	--

Brake System

Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
-----------------------	---	------------------------	---

Brake Fluid	✓		
-------------	---	--	--

Pedals	✓		
--------	---	--	--

Suspension

Shock Absorbers	✓		
-----------------	---	--	--



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight

Left Washer: Washer Cover/ Nozzle Missing



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



Extensive Wear Of Strip

USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	!	Head Rest	✓
Seat Belts	✓	Grab Handle	✓
Door Controls And Trim		Headliner	✓
Rear Left Door: Scratch	!	Toolkit	✓
Carpet	✓		
Rear View Mirror	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE