



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 VOLKSWAGEN TOUAREG**

**SEL | 138,534 KM**

VIN: WVGBC2BP0GD002058

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Memory Seats

Basic Details

 Kilometers	138534	 Specs	Yes
 Engine	3.6L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WVGBC2BP0GD002058		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Rear Defogger	
Central Armrest		Automatic Headlights	



## Exteriors

Fog Light Front



Roof Rails



Running Lights



HID Headlights



## Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



Infotainment System







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door Panel: Low Visual Dent < 30mm		Rear right door Panel: Light Scuffing < 50mm	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


### Quarter Panels Condition

Left Quarter Panel Trim: Light Scuffing<80mm		Right Quarter Panel	
---	---	---------------------	---


### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	
---	---

### Hood Condition

Hood Bonnet: Paint Chip-off < 5mm	
--------------------------------------	---

### Trunk Condition

Trunk Door Trim: Light Scuffing < 50mm, Scuff/ Disfiguration< 50mm	
--	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board		Right Running Board	✓
Front Left Sill Trim: Minor Scuffing < 80mm	!		
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	!
Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm	!	Rim: Alloy Face Light Scuffing < 50mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Face Light Scuffing < 50mm		Rim: Alloy Face/Light Scuffing<50mm	
Spare Alloy/ Rim Condition	✓		

Wheel cover	✓	Antenna	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



## Electricals, Controls & Lights

### Keys

Master Key

Button Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls

Power Seat: Adjuster Switch Fair Use  
Wear/Missing



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch  
Heater Not Working



Parking Sensors



Rear Defogger





USB Charging Port  
Rear: Dummy Cap Missing



Power/ Manual Windows



Seat Heaters



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

4X4 Shifting Knob: Buttons Faded



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Rear Right Door: Fair Use Wear



Grab Handle



Carpet



Headliner

Rear Left: Light Scuffing



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<55%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE