



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 HONDA ACCORD

EX | 109,615 KM

VIN: 1HGCR2641HA618962

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort








Power driver seat





Basic Details

 Kilometers	109615	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1HGCR2641HA618962		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Steering Mounted Audio Controls			
 Exteriors			
Fog Light Front			
 Safety & Security			

Parking Sensors Rear		
 Entertainment		
USB Charging Port		Infotainment System 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Inner Beading: Rubber Crack/ Tear < 5mm



Front right door

Inner Beading: Rubber Crack/ Tear < 5mm



Rear left door

Handle: Paint Chip-off < 5mm



Rear right door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Right Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Paint Chip-off < 5mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Chip < 5mm



Front Bumper Condition

Front Bumper

Condition: Misaligned



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Dent < 50mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar Condition: Light Scuffing<50mm	⚠
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	⚠	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim Alloy Wheel: Rust Damage	⚠

Right Front Alloy/ Rim Alloy Wheel: Rust Damage	⚠	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Grill Condition Scuffing > 50mm	⚠	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition Rear Trunk Panel Dent < 30mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Brake Calipers	✓		

Pedals 

Suspension

Shock Absorbers 

 **Electricals, Controls & Lights**

Keys

Master Key 

Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel

Odometer: Stain 

Airbags

Airbags 

Controls 

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Sunroof Operation

Sunroof 

Lights

Headlight
Left: Scratch 

Interior Lights 

Tail Light Cluster
Right Tail Lamp: Light Scuffing < 50mm 

Turn Signal Lights 

Daylight Running Lights 

License Plate Light 

Fog Lights 

Air Conditioning

AC Air Direction Switch 

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater	✓	Rear Blower Switch	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Colour Faded, Scratch < 50mm, Crack/ Damage < 10mm	!	Central Console Gear Shift Knob: Buttons Faded	!
Cup Holder	✓	Glove Box Glove Box: Scratch	!
Steering Wheel Colour Fade	!	Sunvisor	✓
Seat Upholstery Driver Seat: Stain < 50mm	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet Front Left Floor Mat: Crack & Tear > 30mm	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<85%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE