



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN SUNNY

SV | 93,146 KM

VIN: MDHBN7AD6KG678492

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front

Basic Details

 Kilometers	93146	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MDHBN7AD6KG678492		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Comfort & Convenience			
Steering Mounted Audio Controls		Rear Defogger	



Entertainment

Bluetooth Player



USB Charging Port



USB player



Exteriors

Halogen Headlights



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Frame Extension Cover: Scratch < 50mm

Front right door



Rear left door



Panel: Paint Chip-off < 5mm, Scratch < 50mm

Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Right Quarter Panel



Condition: Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent < 50mm, Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Acid Marks/ Bird Dropping < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover			
Front Right: Edge/ Scuffs < 80mm	!	Antenna	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			

Rear Trunk Panel



Dent < 30mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers

Suspension Noise/ Vibration: Minor Noise
from RR LHS Lower Arm / Link Road/



Stabilizer

Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls



Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Lights

Headlight 

Interior Lights 

Tail Light Cluster 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Rear Defogger 

USB Charging Port 

Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel 

Central Console 

Cup Holder 

Glove Box 

Steering Wheel 

Steering Wheel Fair Use Wear

Sunvisor 

Seat Upholstery 

Manual Seat Movement 

Seat Belts 

Head Rest 

Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<90%

LHS Rear Tyre

<65%

RHS Front Tyre

<90%

RHS Rear Tyre

<55%

Spare Tyre

<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE