



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 BMW X6

35I EXECUTIVE | 102,587 KM

VIN: WBAKU2A08K0Z69066

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat, Memory Seats






























Basic Details

 Kilometers	102587	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WBAKU2A08K0Z69066		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Heads up Display 	Climate Control AC 
Cruise Control 	Memory Seats 
Rear Armrest with cupholder 	Steering Mounted Audio Controls 
Soft Door Close 	Power Folding Mirrors 
Power Tailgate/ Power Trunk 	Rear Defogger 

Central Armrest		Automatic Headlights	
 Safety & Security			
360 degree Camera		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Traction Control		Front Camera	
Side Camera		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		LED Headlights	
 Performance			
Paddle Shift		Hill Descent Control	
 Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door

Panel: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm



Fenders Condition

Left Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
Right B to C Pillar Beading	✓	Light Scuffing < 80mm	!
Running Board Condition		Left C Pillar	✓
Left Running Board	!	Right Running Board	!
Front Left Sill Trim: Scratch < 80mm	!	Right Foot Board: Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	!	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip	!		
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	!
Head Light Support Condition	✓	Beading: Crack/Fair Use Wear<50mm	!
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm	!		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	✓
Rim: Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim	!
Right Front Alloy/ Rim	✓		

		Rim: Alloy Edge/ Scuff < 80mm	
Wheel cover	✓	Antenna	✓
Grill Condition	⚠	Monogram	⚠
Light Scuffing < 50mm		Acid Marks/ Bird Dropping < 5mm	
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Battery

Battery Terminal & Tightness ✓

Fuel System

Fuel Tank ✓

Transmission Operation

Gear Shifting ✓ Gear shift ✓

Drive Axle ✓ 4*4 Condition (If Applicable) ✓

Transmission Fluid ✓

Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake ✓ Brake Master Cylinder ✓

Brake Disc & Brake Pad ✓ Brake Fluid ✓

Pedals 

Suspension

Shock Absorbers 

 **Electricals, Controls & Lights**

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Cruise Control 

Heads Up Display 

Infotainment Display 

Engine Sensors 


OBD Connector 

Radar (If Equipped) 

Navigation System 

Music System 

Sunroof Operation

Sunroof 

Camera 

Lights

Headlight 

Interior Lights 

Tail Light Cluster 

Turn Signal Lights 

Daylight Running Lights 

License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Trim: Light Scuffing/Disfiguration	!	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Fair Use Wear	!	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE