



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2012 KIA SPORTAGE**

**EX | 185,357 KM**

**VIN: KNAPC8119C7209841**

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>185357</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>KNAPC8119C7209841</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	

Rear Defogger		Central Armrest	
Automatic Headlights			
<b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
<b>Entertainment</b>			
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door

Panel: Paint Chip-off < 5mm, Dent < 30mm,



Scratch < 50mm

Rear right door

Frame: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint



Chip-off < 5mm

Right Fender

Condition: Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel



Trim: Light Scuffing<80mm

Right Quarter Panel

Condition: Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip<



8mm

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing



< 50mm

Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm



Trunk conditon

Trunk



Roof Condition

Roof  
Roof Moulding Condition: Colour fade



#### Pillars Condition

Left A Pillar  
Inner Condition: Fair Use Wear



Right A Pillar  
Inner Condition: Light Scuffing



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



#### Running Board Condition

Left Running Board



Right Running Board



#### Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Sunroof Not working

#### Windshield Condition

##### Front Windshield

Condition: Driver Side/Stone Chip  
Mark<5mm, Passenger Side/Stone Chip  
Mark<8mm



Rear Windshield



#### Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Door Skirting: Colour Mismatch/ Fade/ Fair



Use Wear

Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top



#### Rear View Mirror Condition

Left Hand Side Mirror  
Body: Damaged Mirror Casing



Left Side Mirror



Right Side Mirror



Body: Scratch < 50mm

Right Hand Side Mirror



Alloy Wheel/ Rim		
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim
Rim: Alloy Edge Scuffing > 50mm		✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim
Spare Alloy/ Rim Condition	✓	
Wheel cover	✓	Antenna
Grill Condition	!	Monogram
Light Scuffing < 50mm		Paint Chip-off < 5mm
Window Glass	✓	Wiper
		Rear Wiper Blade: Crack/ Fair Use Wear
Panel Condition		
Rear Trunk Panel	✓	

---

## Engine & Transmission

Engine		
Engine Body	✓	Engine Performance
Engine Oil (Condition & Level)	✓	Exhaust System
Radiator Condition	✓	Radiator Coolant
Battery		
Battery Terminal & Tightness	✓	
Fuel System		
Fuel Cap	✓	Fuel Tank
Transmission Operation		
Gear Shifting	✓	Drive Axle
4*4 Condition (If Applicable)	✓	Transmission Fluid

---

## Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Brake Master Cylinder	✓	Brake Disc & Brake Pad

Brake Fluid	
Pedals	
Suspension	
Shock Absorbers	

## Electricals, Controls & Lights

Keys			
Master Key			
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			
Airbags			
Airbags			
Controls		Cruise Control	
Infotainment Display		Engine Sensors	
OBD Connector		Music System	
Sunroof Operation			
Sunroof			
Curtain: Shade Movement Limited			
Lights			
Headlight		Interior Lights	
Left: Light Scuff Marks < 50mm			
Tail Light Cluster		Turn Signal Lights	
Left Tail Lamp: Crack / Fair Use Wear < 5mm			
License Plate Light		Fog Lights	
		Left Fog Light: Lamps Not Working	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	

Front Right AC Vent	✓	Heater Heater Not Working RHS	!
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

---

## Interiors & Luggage

Dashboard And Instrument Panel	!	Central Console	!
Dashboard Trim: Light Scuffing/Disfiguration		Box: Minor Crack/Fair Use Wear/ Scuffing	
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	!
Color Faded		Left: LHS Sunvisor Holder Crack/ Broken	
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Fair Wear/Fade off			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim			
Front Right Door: Fair Use Wear, Light Scuffing/Disfiguration	!	Grab Handle	✓
Carpet	!	Headliner	!
Front Left Floor Mat: Smudge/Burn/Crack		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

---

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE