



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 HYUNDAI VELOSTER

TURBO | 143,992 KM

VIN: KMHTC61E6GU259480

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat, Ventilated Seats




Basic Details

 Kilometers	143992	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	4 Seats	 Number of keys	1 Keys
 VIN number	KMHTC61E6GU259480		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Power Folding Mirrors	
Ventilated Seat		Central Armrest	
Automatic Headlights			
 Exteriors			

Fog Light Front	✓	Running Lights	✓
Rear Bumper Spoiler	✓	Halogen Headlights	✓
 Performance			
Paddle Shift	✓		
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 


Exterior

Doors condition

Front left door

Frame Extension Cover: Low Visual Dent < 30mm 

Front right door


Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm, Paint Chip-off < 5mm 

Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 

Fenders Condition

Left Fender


Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm, Scuffing > 50mm 

Right Fender

Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm 

Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm, Low Visual Dent<30mm, Chip<5mm 

Right Quarter Panel


Condition: Light Scuffing<50mm 

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Refurbished to RTA standards 

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm, Paint Chip-off < 5mm 

Trunk Condition


Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof


Roof Moulding Condition: Minor Rubber Beading Fair Use Wear 

Pillars Condition


Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading Beading Crack/ Tear < 5mm 

Right A to B Pillar Beading 

Right A to B Pillar 

Left B Pillar Condition: Light Scuffing Scratch < 50mm, Low Visual Dent < 30mm 

Left B Pillar Trim 


Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Running Board Condition

Left Running Board Condition: Light Scuffing < 80mm 

Right Running Board Rear Right Sill Trim: Low Visibility Dent < 50mm 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass Sunroof Not working 

Windshield Condition

Front Windshield 


Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor Door Skirting: Colour Mismatch/ Fade/ Fair Use Wear 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition















Left Hand Side Mirror Body: Light Scuffing < 50mm 

Left Side Mirror 

Right Side Mirror Body: Light Scuffing < 50mm		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Paint Faded		Left Rear Alloy/ Rim Rim: Paint Faded	
Right Front Alloy/ Rim Rim: Paint Fade/Paint Defect		Right Rear Alloy/ Rim Rim: Paint Faded/Light Rusting	
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition Light Scuffing < 50mm		Monogram Colour Mismatch/ Fade/ Fair Use Wear	
Window Glass		Wiper	
Panel Condition Rear Trunk Panel Scratch < 50mm			

Engine & Transmission

Engine

Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		Transmission Fluid	

Steering, Suspension & Brakes

Steering

Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys			
Master Key			
Remote/Functions Not Responding	!		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	!
		Condition: Not Working	
Music System			
Condition: Button(s) Faded	!		
Sunroof Operation			
Sunroof			
Curtain: Restricted Movement	!		
Camera	✓		
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓

Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger Not Working	!	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Trim: Light Scuffing/Disfiguration	!	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage	!
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	!	Carpet	✓
Headliner Front Left: Light Smudge/Disfiguration	!	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE