



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2014 CHEVROLET CRUZE LT | 159,722 KM

VIN: KL1PM6D56EK597637

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Safety & Security				
Reverse Camera	~	Blind Spot Monitor	~	
Airbag Driver Front	~	ABS	✓	
Central Locking	~	Child Safety Locking	✓	
्रा Entertainment				
Bluetooth Player	~	Infotainment System	~	
USB player	~			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality





Exterior

Doors condition

Front left door

Handle: Paint Chip-off < 5mm

(!)

(!)

(!)

(!)

Front right door

Handle: Paint Chip-off < 5mm

Rear left door

Handle: Paint Chip-off < 5mm

Rear right door

Handle: Paint Chip-off < 5mm

Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm Right Fender

Condition: Low Visual Dent < 30mm, Paint

(!)

Chip-off < 5mm, Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel

Condition: Acid Marks/ Bird Dropping<5mm,

Light Scuffing<50mm

Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light

Scuffing<50mm

Front Bumper Condition

Front Bumper

Condition: Fair Use Wear

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip<

8mm

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visibility Dent < 30mm

Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm

(!)

Trunk conditon


Trunk




Roof Condition

Roof	✓		
Pillars Condition Left A Pillar			
Inner Condition: Fair Use Wear	!	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	~
Right A to B Pillar	✓	Left B Pillar	~
Left B Pillar Trim	✓	Left B to C Pillar Beading	~
Right C Pillar Trim	✓	Right B to C Pillar	~
Right B to C Pillar Beading	✓	Left C Pillar	~
Running Board Condition Left Running Board Front Left Sill Trim: Scratch < 80mm	(!)	Right Running Board Condition: Dent > 50mm, Scuffing > 80mm	(!)
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Light Scuffing<50mm, Passenger Side/Stone Chip Mark<8mm	(!)	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	~
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			

Left Front Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm	(!)	Left Rear Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm	
Right Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing < 80mm	(!)	Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing<80mm, Alloy Face/Light Scuffing<50mm	(!)
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Scuffing > 50mm	(!)	Monogram	✓
Window Glass	•	Wiper	✓
Panel Condition Rear Trunk Panel Scratch < 50mm	(!)		
Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	~
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			





Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE