



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 CHEVROLET MALIBU**

**LS | 145,630 KM**

VIN: KL1ZA5CA2HB731896

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>145630</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KL1ZA5CA2HB731896</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Cruise Control	
Steering Mounted Audio Controls	
Central Armrest	
Steering Column Adjuster	
 <b>Safety &amp; Security</b>	

Parking Sensors Rear	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓



### Exteriors

Running Lights	✓	Halogen Headlights	✓
----------------	---	--------------------	---



### Entertainment

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Dent < 30mm, Scratch < 50mm

Panel: Low Visual Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender

Condition: Dent > 30mm, Scratch < 50mm,



Paint Chip-off < 5mm

Right Fender: Dent < 30mm, Scratch <

50mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm,



Paint Chip-off < 5mm

Condition: Scratch < 50mm, Paint Chip-off <

5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Damage/ Low Brightness, Paint

Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Scuff/ Disfiguration< 50mm, Light

Scuffing < 50mm

Trunk conditon

Trunk



Pillars Condition

Left A Pillar	!	Right A Pillar	✓
Inner Condition: Fair Use Wear			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	!	Right Running Board	
Condition: Paint Defect		Condition: Low Visual Dent < 50mm, Light Scuffing < 80mm, Paint Defect	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	
		Beading: Crack/Fair Use Wear < 50mm	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover	!	Antenna	✓
Rear Right: Edge/ Scuffs < 80mm			
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓

## Panel Condition

Rear Trunk Panel



## ⌚ Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## 擐 Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## 📅 Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)

Button Faded



Buttons Faded

Door Locks

Child Safety Locking 

Dashboard 

Instrument Panel 

Airbags 

Airbags 

Controls 

Cruise Control

Cruise Control Switch: Buttons Faded



Infotainment Display 

Engine Sensors 

OBD Connector 

Navigation System

Condition: Available - Android Auto & Apple



CarPlay

Music System

Steering Mounted Audio Controls: Button(s) 

Faded

Lights

Headlight 

Interior Lights 

Tail Light Cluster 

Daylight Running Lights 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Rear Blower Switch 

Rear Defogger 

USB Charging Port 

Power/ Manual Windows 

## **Interiors & Luggage**

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/  Fair Use Wear

Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing,  Minor Color Low Brightness

Cup Holder	✓	Glove Box	
Steering Wheel	!	Glove Box: Minor Scuffing/Crack/Fair Use Wear, Glove Box Retainer Faulty	!
Steering Wheel Fair Use Wear			
Seat Upholstery		Sunvisor	✓
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Front Left Door: Light Scuffing			
Carpet	!	Headliner	!
Front Left Floor Mat: Smudge/Burn/Crack		Rear Left: Smudge/Disfiguration, Fair Use Wear	
Rear View Mirror	!	Toolkit	✓
De Silvered Mirror<10%			

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE