



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 NISSAN MAXIMA

S | 58,912 KM

VIN: 1N4AA6AP0JC379734

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort









Power driver seat


Basic Details

 Kilometers	58912	 Specs	Yes
 Engine	3.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	1N4AA6AP0JC379734		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Central Armrest			
 Exteriors			
Fog Light Front		Running Lights	
 Safety & Security			

Navigation	✓	Parking Sensors Rear	✓
Reverse Camera	✓	ABS	✓
Central Locking	✓		
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓		





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Condition: Scratched, Dented		Condition: Chrome Chipped, Scratched	
Rear left door		Rear right door	
Condition: Scratched, Dented		Condition: Scratched	

Fenders Condition

Left Fender		Right Fender	
Condition: Scratched		Right Fender: Scratched	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratched		Condition: Scratched, Dented	

Front Bumper Condition

Front Bumper	
Condition: Scratched	

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched, Misaligned	








Hood Condition

Hood	
Bonnet: Scratched	

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Condition: Scratched			
Left B Pillar		RHS Pillar B Condition	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

Running Board Condition

Left Running Board
Condition: Scratched



Right Running Board
Condition: Scratched



Windshield Condition

Front Windshield
Condition: Air Bubbles



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Alloy Wheel: Scratched

Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Alloy Wheel: Scuff Marks

Alloy Wheel: Scuff Marks

Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Faded



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Transmission Operation	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		






Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Navigation System	✓
Music System	✓	Bluetooth Operations	✓
Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight	!	Interior Lights	✓

Left: Faded			
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Trim Stained, Trim Scratched	!
Cup Holder	✓	Sunvisors Cover Torn	!
Seat Upholstery Driver Seat: Faded	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues Rear Seat Belt Stained	!
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE