



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2019 CHEVROLET AVEO

LS | 92,932 KM

VIN: KL1JD5CE2KB100130

### Car highlights



#### **Bluetooth**

Enjoy your drive with bluetooth



#### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



#### **Amazing Comfort**
















Power driver seat



#### **Airbag safety**










Airbag Driver Front

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 92932             |  Specs             | Yes                  |
|  Engine           | 1.4L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             |  Fuel              | Petrol               |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | KL1JD5CE2KB100130 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |  |   |                     |   |
|--|--|---|---------------------|---|
|  <b>Safety &amp; Security</b>     |  |   |                     |   |
| Traction Control   |  |  | Airbag Driver Front |  |
| ABS  |  |  | Central Locking     |  |
| Child Safety Locking   |  |  |                     |   |
|  <b>Comfort &amp; Convenience</b> |  |   |                     |   |
| Steering Mounted Audio Controls  |  |  | Rear Defogger       |  |



## Entertainment

Bluetooth Player



USB Charging Port



USB player



## Exteriors

Halogen Headlights







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                        |   |                             |   |
|------------------------|---|-----------------------------|---|
| Front left door        |  | Front right door            |  |
| Handle: Scratch < 50mm |   |                             |   |
| Rear left door         |  | Rear right door             |  |
| Panel: Scratch < 50mm  |   | Panel: Paint Chip-off < 5mm |   |

### Fenders Condition

|   |   |                                 |   |
|---|---|---------------------------------|---|
| Left Fender                                   |   | Right Fender                    |   |
| Condition: Light Scuffing < 50 mm, Low Visual |  | Condition: Paint Chip-off < 5mm |  |
| Dent < 30mm                                   |   |                                 |   |


### Quarter Panels Condition

|                                 |   |                     |   |
|---------------------------------|---|---------------------|---|
| Left Quarter Panel              |  | Right Quarter Panel |  |
| Condition: Paint Chip-off < 5mm |   |                     |   |


### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper                                   |   |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |

### Hood Condition

|  |   |
|--|---|
| Hood   |   |
| Inner Protection Cover: Clip Fair Use Wear/ Falling Down |  |

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

|                              |   |   |   |
|------------------------------|---|---|---|
| Pillars Condition            |   |   |   |
| Left A Pillar                | ✓ | Right A Pillar                              | ✓ |
| Left A to B Pillar Beading   | ✓ | Right A to B Pillar Beading                 | ✓ |
| Right A to B Pillar          | ✓ | Left B Pillar                               | ✓ |
| Left B Pillar Trim           | ✓ | Left B to C Pillar Beading                  | ✓ |
| Right C Pillar Trim          | ✓ | Right B to C Pillar                         | ✓ |
| Right B to C Pillar Beading  | ✓ | Left C Pillar                               | ✓ |
| Running Board Condition      |   |   |   |
| Left Running Board           | ⚠ | Right Running Board                         | ⚠ |
| Condition: Scratch < 80mm    |   | Rear Right Sill Trim: Light Scuffing < 80mm |   |
| Windshield Condition         |   |   |   |
| Front Windshield             | ✓ | Rear Windshield                             | ✓ |
| Structural Assessment        |   |   |   |
| Chassis Condition            | ✓ | Radiator Support                            | ✓ |
| Apron                        | ✓ | Boot Floor                                  | ✓ |
| Firewall Condition           | ✓ | Cowl Top                                    | ✓ |
| Head Light Support Condition | ✓ |   |   |
| Cowl Top                     |   |   |   |
| Cowl Top                     | ✓ |   |   |
| Rear View Mirror Condition   |   |   |   |
| Left Hand Side Mirror        | ✓ | Left Side Mirror                            | ✓ |
| Right Side Mirror            | ✓ | Right Hand Side Mirror                      | ✓ |
| Alloy Wheel/ Rim             |   |   |   |
| Spare Alloy/ Rim Condition   | ✓ |   |   |
| Wheel cover                  | ✓ | Antenna                                     | ✓ |
| Grill Condition              | ⚠ | Monogram                                    | ✓ |
| Light Scuffing < 50mm        |   |   |   |
| Window Glass                 | ✓ | Wiper                                       | ✓ |
| Panel Condition              |   |   |   |

Rear Trunk Panel  
Paint Chip Off < 5mm



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



|                     |   |                       |   |
|---------------------|---|-----------------------|---|
| Dashboard           |   |                       |   |
| Instrument Panel    | ✓ |                       |   |
| Airbags             |   |                       |   |
| Airbags             | ✓ |                       |   |
| Controls            | ✓ | Infotainment Display  | ✓ |
| Engine Sensors      | ✓ | OBD Connector         | ✓ |
| Music System        | ✓ |                       |   |
| Lights              |   |                       |   |
| Headlight           | ✓ | Interior Lights       | ✓ |
| Tail Light Cluster  | ✓ | License Plate Light   | ✓ |
| Air Conditioning    |   |                       |   |
| AC Cooling          | ✓ | AC Switch             | ✓ |
| AC System Leaks     | ✓ | Center AC Vent        | ✓ |
| Front Right AC Vent | ✓ | Heater                | ✓ |
| USB Charging Port   | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

|   |   |  |   |
|---|---|--|---|
| Dashboard And Instrument Panel                            | ✓ | Central Console<br>Gear Shift Knob: Knob Fair Use Wear | ! |
| Cup Holder  | ✓ | Glove Box  | ✓ |
| Steering Wheel  | ✓ | Sunvisor   | ✓ |
| Seat Upholstery<br>Driver Seat: Minor Smudge/ Cracks      | ! | Manual Seat Movement                                   | ✓ |
| Seat Belts  | ✓ | Head Rest  | ✓ |
| Door Controls And Trim<br>Front Left Door: Light Scuffing | ! | Grab Handle  | ✓ |
| Carpet  | ✓ | Headliner  | ✓ |



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

No spare  
tyre



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE