



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 RENAULT SYMBOL

LE | 87,102 KM

VIN: VF14SRAB0HT518635

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat

Basic Details

 Kilometers	87102	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Partial Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF14SRAB0HT518635		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience				
Climate Control AC			Cruise Control	
 Exteriors				
Fog Light Front			Running Lights	
 Safety & Security				
Navigation			Parking Sensors Rear	

Reverse Camera



Traction Control



150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition


Front left door

Moulding: Scratch < 50mm, Paint Chip-off < 5mm 

Front right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door


Handle: Scratch < 50mm, Paint Chip-off < 5mm 

Rear right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Fenders Condition

Left Fender


Condition: Paint Chip-off < 5mm, Scratch < 50mm 

Right Fender


Right Fender: Scratch < 50mm, Paint Chip-off < 5mm 

Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm 


Right Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm 

Front Bumper Condition


Front Bumper 

Rear Bumper Condition

Rear Bumper 
Rear Bumper: Scuffing > 80mm, Chip< 8mm

Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading Beading Crack/ Tear < 5mm	!
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading Beading Crack/ Tear < 5mm	!
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading Beading Crack/ Tear < 5mm	!	Left C Pillar	✓
Running Board Condition			
Left Running Board Rear Left Sill Trim: Scratch < 80mm	!	Right Running Board Rear Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Condition: Light Scuffing < 80mm	!
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim	✓

Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/ Scuff < 50mm	⚠		✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition		Monogram	✓
Light Scuffing < 50mm	⚠		
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	⚠		

🔧 Engine & Transmission


Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering

Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓
Music System	✓	Camera	✓
Lights			
Headlight		Interior Lights	✓
Right: Light Scuff Marks < 50mm	!		
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent		Heater	✓
Fair Use Wear	!		

Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard And Instrument Panel: Light Scuffing/ Disfiguration/Melted, Light Scuffing/Crack	!	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery			
Driver Seat: Minor Cigarette Burn	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	
		Front Left: Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE