



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 MITSUBISHI LANCER EX**

**GLS | 120,912 KM**

VIN: JMYSRCY1AGU757566

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Music System**














Enjoy your drive with music system



### **Amazing Comfort**










Power driver seat









## Basic Details

 Kilometers	<b>120912</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic Option</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
Seating Capacity	<b>5 Seats</b>	Number of keys	<b>2 Keys</b>
 VIN number	<b>JMYSRCY1AGU757566</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 <b>Exteriors</b>			
Fog Light Front		Rear Bumper Spoiler	

Halogen Headlights			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

#### Front left door

Weather Strip: Chrome Low Brightness



#### Front right door

Panel: Light Scuffing < 50mm, Low Visibility



Dent < 30mm

#### Rear left door

Panel: Light Scuffing < 50mm, Low Visual



Dent < 30mm

#### Rear right door

Panel: Low Visual Dent < 30mm



### Fenders Condition

#### Left Fender



#### Right Fender



### Quarter Panels Condition

#### Left Quarter Panel

Condition: Light Scuffing<50mm, Dent > 30mm



#### Right Quarter Panel



### Front Bumper Condition

#### Front Bumper



### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

#### Hood

Bonnet: Low Visibility Dent < 30mm



### Trunk Condition

#### Trunk



### Trunk conditon

#### Trunk



### Roof Condition

#### Roof



### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Light Scuffing < 50mm	⚠
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm	⚠	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm	⚠
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing<80mm	⚠

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body Mount Condition: Minor Crack/Fair Use Wear	!	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



Power/ Manual Windows



## Interiors & Luggage



Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear		Left: Sunvisor LHS Vanity Mirror Cover Damage	
Seat Upholstery		Manual Seat Movement	
Driver Seat: Minor Smudge/ Cracks			
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Front Left Floor Mat: Smudge/Burn/Crack			
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE