



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2013 DODGE CHARGER

R/T | 155,865 KM

VIN: 2C3CDXCT8DH715548

Car highlights



Power packed

Engine size of 5.7 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat



















Basic Details

 Kilometers	155865	 Specs	Yes
 Engine	5.7L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	2C3CDXCT8DH715548		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Central Armrest		Remote Engine Start	
Automatic Headlights			
 Exteriors			

Fog Light Front		Running Lights	
Rear Bumper Spoiler		Halogen Headlights	
HID Headlights			
 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Curtain Shield		Airbag Knees	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility



Dent < 30mm, Paint Chip-off < 5mm

Rear left door

Panel: Light Scuffing < 50mm, Low Visual



Dent < 30mm, Paint Chip-off < 5mm

Rear right door

Panel: Light Scuffing < 50mm, Colour



Mismatch/ Low Brightness, Dent > 30mm

Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light



Scuffing < 50 mm

Right Fender

Condition: Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm, Light



Scuffing<50mm

Right Quarter Panel

Condition: Low Visual Dent < 30mm, Colour



Mismatch, Light Scuffing<50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Minor Color



Dullness

Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar Condition: Light Scuffing Scratch < 50mm	!
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	!
Right B to C Pillar Beading	✓	Left C Pillar Light Scuffing < 50mm	!
Running Board Condition			
Left Running Board Condition: Scuffing > 80mm, Fair Use Wear	!	Right Running Board Condition: Scuffing > 80mm	!
Windshield Condition			
Front Windshield Condition: Scuffing>50mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	
Firewall Condition	✓	Door Skirting: Colour Mismatch/ Fade/ Fair Use Wear	!
Head Light Support Condition	✓	Cowl Top	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Light Scuffing < 50mm	!	Left Side Mirror Not Working Properly	!
Right Side Mirror Body: Paint Defects, Paint Chip-off < 5mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm	!
Right Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm	!	Right Rear Alloy/ Rim Rim: Alloy Face/Light Scuffing<50mm	!

Spare Alloy/ Rim Condition			
Wheel cover		Grill Condition	
Front Left: Wheel Nut/Screw Cover		Scuffing > 50mm	
Damaged/Fair Use Wear			
Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Dent < 30mm			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Damage & Leaks: Engine Vibration By Characteristics		Exhaust System	
Engine Oil (Condition & Level)		Radiator Coolant	
Radiator Condition			
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Front Left: minor imperfection			

Pedals 

Suspension

Shock Absorbers 

 **Electricals, Controls & Lights**

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Cruise Control 


Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Lights

Headlight
Left: Light Scuff Marks < 50mm 

Interior Lights 

Tail Light Cluster 

Daylight Running Lights 

License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 


Center AC Vent 

Front Right AC Vent 

Heater
Heater Not Working 

Rear Blower Switch 

Parking Sensors 

Rear Defogger
Extensive Wear Of Strip 

USB Charging Port		Power/ Manual Windows	
Seat Heaters			

Interiors & Luggage

Dashboard And Instrument Panel		Central Console Box: Minor Disfiguration	
Cup Holder		Glove Box	
Steering Wheel Steering Wheel Fair Use Wear		Sunvisor	
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest Front Right Seat: Fair Use Wear	
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration		Grab Handle	
Carpet Front Left Floor Mat: Smudge/Burn/Crack		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE