



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 MERCEDES BENZ C 200**

**AMG | 89,505 KM**

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat, Memory Seats & more



Basic Details

 Kilometers	89505	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	COUPE	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Leather Trim	 Number of Airbags	9 Airbags
 Seating Capacity	4 Seats	 Number of keys	1 Keys
 VIN number	WDDWJ4CB2HF469620		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Central Armrest	
 <b>Safety &amp; Security</b>			
Lane Departure Warning		Parking Sensors Front	

System	
Navigation	✓
Reverse Camera	✓
ABS	✓
 <b>Exteriors</b>	
Running Lights	✓
 <b>Entertainment</b>	
Bluetooth Player	✓
Infotainment System	✓
Parking Sensors Rear	✓
Front Camera	✓
Central Locking	✓
USB Charging Port	✓

## 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



### Exterior

#### Doors condition

Front left door



Front right door



Rear left door



Rear right door



#### Fenders Condition

Left Fender



Right Fender



#### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel  
Condition: Scratched



#### Front Bumper Condition

Front Bumper



Condition: Dented

#### Rear Bumper Condition

Rear Bumper



#### Hood Condition

Hood



Bonnet: Scratched

#### Trunk conditon

Trunk



#### Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



#### Running Board Condition

Left Running Board



Right Running Board



## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Alloy Wheel: Scratched



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim  
Alloy Wheel: Scratched



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel Condition: Trim Scratched	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Bluetooth Operations	✓		
Sunroof Operation			
Sunroof	✓		

Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight	✓	Interior Lights	✓
Tail Light Cluster	⚠	Turn Signal Lights	✓
Right Tail Lamp: Broken			
License Plate Light	✓	Back Up Light	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Cover Missing, Trim Scratched	⚠
Sunvisors	✓	Seat Upholstery Driver Seat: Scratched	⚠
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Torned	⚠	Door Hinge Condition	✓



Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE