



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2016 CHEVROLET TRAVERSE

LS | 44,661 KM

VIN: 1GNKR8EDXGJ255355

### Car highlights



#### Low Mileage

This car has been driven less than 15,000 km  
a year



#### Cruise control

Cruise control to drive with ease & comfort



#### Music System
















Enjoy your drive with music system



#### Tilt Steering wheel








Tilt steering wheel for extra comfort







Basic Details

 Kilometers	44661	 Specs	Yes
 Engine	3.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	3 Keys
 VIN number	1GNKR8EDXGJ255355		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>				
Cruise Control			Steering Mounted Audio Controls	
 <b>Exteriors</b>				
Fog Light Front			Running Lights	
 <b>Safety &amp; Security</b>				

Parking Sensors Rear		ABS	
Central Locking			
 <b>Entertainment</b>			
USB Charging Port		Infotainment System	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Condition: Faded, Dented			

Rear left door		Rear right door	
Condition: Faded, Dented		Condition: Scratched	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

### Front Bumper Condition

Front Bumper	
Condition: Scratched	

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched	

### Hood Condition

Hood	
Bonnet: Scratched	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
		Condition: Scratched	

Left B Pillar		RHS Pillar B Condition	
		Faded	

RHS Pillar C Condition		Left C Pillar	
------------------------	---	---------------	---

Left D pillar	
---------------	---

### Running Board Condition

Left Running Board	✓	Right Running Board Condition: Dented	!
Windshield Condition			
Front Windshield Condition: Air Bubbles	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor Condition: Torn/Damaged	!	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratched	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Window Glass Front Left: Beading Faded	!	Wiper	✓
Panel Condition			
Rear Trunk Panel Scratched	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓

Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Transmission Operation	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Condition: Trim Faded	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Radar (If Equipped)	✓
Music System	✓		
Lights			
Lights	✓	Running lights	✓
Headlight			
Left: Scratched	!	Interior Lights	✓

Tail Light Cluster	!	Turn Signal Lights	✓
Left Tail Lamp: Faded			
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Trim Scratched	!	Condition: Rear AC Vent Missing	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Depressed/Pressure Mark	!		
Seat Belts		Seat Belt with issues	✓
Movement & Locking: LHS Rear Seat Belt Buckle Missing/Not Working	!		
Head Rest	✓	Door Controls And Trim	!
		Front Left Door: Scratched	
Door Hinge Condition	✓	Carpet	✓
Headliner		Rear View Mirror	✓
Headliner condition: Torn/Dirty	!		
Toolkit			
Luggage Compartment: Scratched	!		



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<45%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE