



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 BMW 750Li

XDRIVE | 10,697 KM

VIN: WBA7F2A04KB236324

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort



Rear Seat Entertainment
















Enjoy your drive with Rear Seat Entertainment



Amazing Comfort











Power driver seat, Memory Seats & more

Basic Details

 Kilometers	10697	 Specs	Yes
 Engine	4.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WBA7F2A04KB236324		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Rear Seat Entertainment	
Steering Mounted Audio Controls		Power Sliding Doors	
Heads up Display		Power Tailgate/ Power Trunk	
Central Armrest			



Exteriors

Fog Light Front



Running Lights



Safety & Security

Lane Departure Warning
System



Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Front Camera



Side Camera



ABS



Central Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Power Sliding Doors	
---------------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left B Pillar		RHS Pillar B Condition	
---------------	---	------------------------	---

RHS Pillar C Condition		Left C Pillar	
------------------------	---	---------------	---

Left D pillar	
---------------	---

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		
<hr/>			
 Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓

Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Heads Up Display	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓	Bluetooth Operations	✓
Sunroof Operation			
Sunroof	✓		

Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Parking Sensors



Rear Defogger



USB Charging Port



Rear Entertainment



Power/ Manual Windows



Seat Heaters



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Sunvisors



Seat Upholstery



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim



Door Hinge Condition



Carpet



Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE