



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 JAGUAR F TYPE

S | 65,335 KM

VIN: SAJAA64J5F8K13075

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 65335 |  Specs | Yes |
|  Engine | 3.0L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Rear Wheel Drive |
|  Body Type | CONVERTIBLE |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 4 Airbags |
|  Seating Capacity | 2 Seats |  Number of keys | 1 Keys |
|  VIN number | SAJAA64J5F8K13075 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | |
|--|---|
| Climate Control AC  | Steering Mounted Audio Controls  |
| Rear Defogger  | Central Armrest  |
| Automatic Headlights  | Steering Column Adjuster  |
|  Performance | |
| Paddle Shift  | |



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Exteriors

Running Lights



HID Headlights



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel
Trim: Light Scuffing < 80mm



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood
Bonnet: Acid Marks/ Bird Dropping > 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



| | | | |
|--|--|------------------------------|--|
| Right A to B Pillar | | Left B Pillar | |
| RHS Pillar B Condition | | RHS Pillar C Condition | |
| Left D pillar | | | |
| Running Board Condition | | | |
| Left Running Board | | Right Running Board | |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | | | |
| Windshield Condition | | | |
| Front Windshield | | | |
| Beading: Mouldings Crack/ Fair Use Wear > 50mm | | Rear Windshield | |
| Structural Assessment | | | |
| Chassis Condition | | Apron | |
| Boot Floor | | Firewall Condition | |
| Cowl Top | | Head Light Support Condition | |
| Beading: Crack/Fair Use Wear>50mm | | | |
| No structural damage | | | |
| Chassis Conditon | | Upper Cross Member Condition | |
| Lower Cross Member Condition | | Chassis Condition | |
| Radiator Support | | | |
| Cowl Top | | | |
| Cowl Top | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Left Side Mirror | |
| Right Side Mirror | | Right Hand Side Mirror | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | | Left Rear Alloy/ Rim | |
| Right Front Alloy/ Rim | | Right Rear Alloy/ Rim | |
| Wheel cover | | Antenna | |

| | | | |
|------------------|---|----------|---|
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

Engine

| | | | |
|--------------------------------|---|--------------------|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | Transmission Fluid | ✓ |
| Transmission Operation | ✓ | | |

Steering, Suspension & Brakes

Steering

| | | | |
|---|---|-----------------------|---|
| Steering wheel Condition: Trim Scratched | ⚠ | Shock absorbers | ✓ |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Suspension | | | |
| Suspension | ✓ | Shock Absorbers | ✓ |



Electricals, Controls & Lights

Keys

Master Key



Remote Key Operations

Keyless/ Remote Start



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Cruise Control



Heads Up Display



Infotainment Display



OBD Connector



Music System

Condition: Button(s) Faded



Bluetooth Operations



Sunroof Operation

Sunroof



Lights

Lights



Running lights



Headlight

Left: Cracks/ Holes, Low Brightness lamps



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Back Up Light



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



| | | | |
|----------------------------|---|-----------------------|---|
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| AC Heater Operation Switch | ✓ | AC Blower Switch | ✓ |
| AC Wind Direction | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |
| Memory Seats | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Gear Shift Knob: Buttons Faded | ⚠ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisors | ✓ |
| Sunvisor | ✓ | Seat Upholstery Driver Seat: Minor Fair Wear/Fade off, Minor Leather/ Fabric Fair Use Wear/ Tears | ⚠ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Seat Belt with issues | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Door Hinge Condition | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|---|---------------------------|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Tyres Depth (Remaining) | | | |

| | | | |
|----------------|------------------|---------------|------|
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | No spare tyre | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE