



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 CHEVROLET MALIBU**

**LS | 69,460 KM**

VIN: KL1GD5CU0FB009364

## **Car highlights**



### **Bluetooth**

Enjoy your drive with bluetooth



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**
















Power driver seat



### **Central Arm Rest**




Central arm rest for extra comfort

Basic Details

 Kilometers	69460	 Specs	Yes
 Engine	2.4L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KL1GD5CU0FB009364		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls		✓	Central Armrest
			✓
 <b>Entertainment</b>			
Bluetooth Player		✓	Infotainment System
			✓
 <b>Safety &amp; Security</b>			

ABS



Central Locking







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Condition: Scratched	
Rear left door Condition: Scratched		Rear right door	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---








### Hood Condition

Hood	
------	---

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Left B Pillar		RHS Pillar B Condition	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

### Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

## Windshield Condition

Front Windshield

Condition: Beading Missing/Broken



Rear Windshield



## Structural Assessment

Chassis Condition



Apron



Boot Floor

Condition: Carpet Torn/Damaged



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Wheel cover

Wheel covers Condition: Scratched



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratched



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Transmission Operation



## Steering, Suspension & Brakes

Steering

Steering wheel

Condition: Trim Faded



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



## Electricals, Controls & Lights

Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Controls



Music System



Bluetooth Operations



Lights

Lights



Headlight

Left: Scratched



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
USB Charging Port	✓	Power/ Manual Windows	✓



## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	✓
Dashboard And Instrument Panel: Trim Faded	!		
Cup Holder	✓	Sunvisors	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Cigarette Burn, Stained	!		
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	
		Broken/Not Working	!
Toolkit	✓		



## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<85%		





## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE