



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2013 BMW 650I**

**GRAN COUPE | 57,325 KM**

VIN: WBA6B2107DDG65832

## Car highlights



### **Power packed**

Engine size of 4.4 Litres & 8.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat, Memory Seats



## Basic Details

 Kilometers	<b>57325</b>	 Specs	<b>Yes</b>
 Engine	<b>4.4L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WBA6B2107DDG65832</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Heads up Display		Power Tailgate/ Power Trunk	
Remote Engine Start			
 <b>Exteriors</b>			

Fog Light Front	✓	
 <b>Safety &amp; Security</b>		
Navigation	✓	Parking Sensors Rear ✓
Reverse Camera	✓	Front Camera ✓
Central Locking	✓	
 <b>Entertainment</b>		
Bluetooth Player	✓	USB Charging Port ✓
Infotainment System	✓	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Condition: Beading Missing/Broken,  
Scratched



Front right door

Condition: Scratched



Rear left door

Condition: Scratched



Rear right door

Condition: Beading Missing/Broken



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper

Condition: Scratched



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Trunk condition

Trunk



### Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



### Running Board Condition


Left Running Board  
Condition: Scratched 

Right Running Board  
Condition: Scratched 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield  
Condition: Sensor Faded 

Rear Windshield 

Structural Assessment

Chassis Condition 

Apron 

Boot Floor 

Firewall Condition 

Head Light Support Condition 

No structural damage

Chassis Condition 

Upper Cross Member Condition 

Lower Cross Member Condition 

Chassis Condition 

Radiator Support 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror 


Left Side Mirror 

Right Side Mirror 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim 

Left Rear Alloy/ Rim 

Right Front Alloy/ Rim 

Right Rear Alloy/ Rim 

Grill Condition 

Window Glass 

Wiper 

Panel Condition

Rear Trunk Panel 

---

## Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

### **Steering, Suspension & Brakes**

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

### **Electricals, Controls & Lights**

Keys			
Master Key Faded	!		
Remote Key Operations			
Keyless/ Remote Start	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Navigation System	✓
Music System	✓	Bluetooth Operations	✓

## Sunroof Operation

Sunroof



## Lights

Lights



Headlight

Left: Faded, Spray Nozzle Missing



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



## Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Parking Sensors

Front Sensors: Not Working



Rear Defogger



USB Charging Port



Power/ Manual Windows



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Push Start  
Button Faded



Central Console

Condition: Fabric Torned



Cup Holder



Sunvisors



Seat Upholstery

Driver Seat: Depressed/Pressure Mark



Manual Seat Movement



Seat Belts



Seat Belt with issues





Head Rest



Door Controls And Trim



Rear Right Door: Scratched

Door Hinge Condition



Carpet



Headliner

Headliner condition: Torn/Dirty



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

No spare

tyre



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE