



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 BMW X5

XDRIVE50I | 101,745 KM

VIN: WBAKR6101E0G95032

Car highlights



Power packed

Engine size of 4.4 Litres & 8.0 cylinders



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat, Memory Seats & more



Basic Details

 Kilometers	101745	 Specs	Yes
 Engine	4.4L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WBAKR6101E0G95032		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Heads up Display		Power Tailgate/ Power Trunk	
Central Armrest		Remote Engine Start	
 Exteriors			

Fog Light Front	✓	Running Lights	✓
 Safety & Security			
Parking Sensors Front	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Front Camera	✓	ABS	✓
Central Locking	✓		
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door
Condition: Scratched



Rear right door



Fenders Condition

Left Fender



Right Fender
Right Fender: Scratched



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel
Condition: Faded



Front Bumper Condition

Front Bumper
Condition: Logo Faded, Scratched



Rear Bumper Condition

Rear Bumper
Rear Bumper: Scratched



Hood Condition

Hood



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar
Condition: Scratched



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratched	!		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel			
Condition: Trim Faded	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Remote Key Operations			
Keyless/ Remote Start	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Radar (If Equipped)	✓

Navigation System	✓	Music System	✓
Bluetooth Operations	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight Right: Scratched	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Faded	!	Central Console Condition: Cover Missing, Scratched	!
Cup Holder	✓	Sunvisors	✓

Seat Upholstery	ⓘ	Manual Seat Movement	✓
Driver Seat: Depressed/Pressure Mark			
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	ⓘ
		Front Right Door: Scratched	
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE