



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 TOYOTA AVANZA

SE | 96,581 KM

VIN: MHKMF5CFXKK007967

Car highlights



Great Parking Assistance

Parking Sensors Rear



Music System

Enjoy your drive with music system



Steering Mounted Audio Controls
















Enjoy your drive with steering mounted audio controls



Central Arm Rest









Central arm rest for extra comfort

Basic Details

 Kilometers	96581	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	3 Keys
 VIN number	MHKMF5CFXKK007967		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors		
Fog Light Front		
 Safety & Security		
Parking Sensors Rear		Central Locking 
 Comfort & Convenience		
Steering Mounted Audio Controls		Central Armrest 



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door  Front right door 

Rear left door  Rear right door 

Fenders Condition

Left Fender  Right Fender 

Quarter Panels Condition

Left Quarter Panel  Right Quarter Panel Condition: Scratched 

Front Bumper Condition

Front Bumper Condition: Scratched 

Rear Bumper Condition

Rear Bumper 

Hood Condition

Hood 

Trunk condition

Trunk 

Pillars Condition

Left A Pillar  Right A Pillar 

Left B Pillar Condition: Scratched  RHS Pillar B Condition Scratched 

RHS Pillar C Condition  Left C Pillar 

Left D pillar 

Running Board Condition

Left Running Board  Right Running Board 

Windshield Condition

Front Windshield

Condition: Beading Missing/Broken



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Condition



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness			
Transmission Operation			
Drive Axle		Transmission Operation	

Steering, Suspension & Brakes

Steering			
Steering wheel		Shock absorbers	
Condition: Trim Faded			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Fluid			
Suspension			
Suspension			
#N/A			

Electricals, Controls & Lights

Keys			
Master Key			
Door Locks			
Central Locking Operation		Child Safety Locking	
Dashboard			
Instrument Panel			
Radar (If Equipped)		Music System	
Lights			
Lights		Headlight	
Interior Lights		Tail Light Cluster	
Turn Signal Lights		License Plate Light	
Back Up Light		Fog Lights	
Trunk Lid Release/Trunk Lid Light Operation			
Air Conditioning			
AC Air Direction Switch		Blower Motor	

Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Scratched	⚠	Central Console Condition: Gear Knob Scratched, Scratched	⚠
Cup Holder	✓	Sunvisors	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE