



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 TOYOTA FORTUNER

EXR | 109,204 KM

VIN: MHFYX59G8F8066273

Car highlights



Four wheel drive

This car has a Four wheel drive



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Central Arm Rest









Central arm rest for extra comfort

Basic Details

 Kilometers	109204	 Specs	Yes
 Engine	2.7L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MHFYX59G8F8066273		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		ABS	
Central Locking			
 Comfort & Convenience			
Steering Mounted Audio Controls		Central Armrest	
 Entertainment			

Bluetooth Player



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Condition: Scratched, Beading Faded



Front right door

Condition: Scratched, Beading Faded, Dented



Rear left door

Condition: Scratched, Beading Faded,
Beading Molten



Rear right door

Condition: Scratched



Fenders Condition

Left Fender

Condition: Scratched



Right Fender

Condition: Scratched



Quarter Panels Condition

Left Quarter Panel

Condition: Scratched



Right Quarter Panel

Condition: Scratched



Front Bumper Condition

Front Bumper

Condition: Misaligned, Scratched



Rear Bumper Condition

Rear Bumper

Rear Bumper: Scratched



Hood Condition

Hood

Bonnet: Faded



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar

Condition: Scratched



RHS Pillar B Condition

Faded









RHS Pillar C Condition



Left C Pillar

Scratched



Left D pillar			
Running Board Condition			
Left Running Board Condition: Scratched		Right Running Board Condition: Scratched	
Windshield Condition			
Front Windshield Condition: Scratched		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Head Light Support Condition			
No structural damage			
Chassis Condition		Upper Cross Member Condition	
Lower Cross Member Condition		Chassis Condition	
Radiator Support			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror Body: Scratched		Left Side Mirror	
Right Side Mirror Body: Faded		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim Alloy Wheel: Scratched		Right Rear Alloy/ Rim	
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel Torned			

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Transmission Operation	✓		

Steering, Suspension & Brakes

Steering

Steering wheel Condition: Trim Faded, Trim Scratched	!	Shock absorbers	✓
---	---	-----------------	---

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Suspension	✓		
------------	---	--	--

Electricals, Controls & Lights

Keys

Master Key	✓		
------------	---	--	--

Door Locks

Central Locking Operation	✓	Child Safety Locking	✓
---------------------------	---	----------------------	---

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Music System

Music System	✓	Bluetooth Operations	✓
--------------	---	----------------------	---

Lights

Lights	✓	Headlight Left: Faded	!
--------	---	--------------------------	---

Interior Lights

Interior Lights	✓	Tail Light Cluster Right Tail Lamp: Scratched	!
-----------------	---	--	---

Turn Signal Lights	✓	License Plate Light	✓
Back Up Light	✓	Fog Lights	!
		Left Fog Light: Faded	
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Trim Scratched	!	Condition: Gear Lever Knob Scratched, Cover Scratched	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Depressed/Pressure Mark, Faded	!		
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	
		Front Left Door: Scratched	!
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE