



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN SENTRA

S | 126,595 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat










Basic Details

 Kilometers	126595	 Specs	Yes
 Engine	1.8L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MNTAB7A93K6010115		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Cruise Control 	Steering Mounted Audio Controls 
Rear Defogger 	Central Armrest 
Steering Column Adjuster 	
 Safety & Security	
Parking Sensors Rear 	Traction Control 

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Exteriors			
Halogen Headlights			
 Entertainment			
Infotainment System		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Dented



Front right door
Condition: Scratched



Rear left door



Rear right door
Condition: Scratched



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
RHS Pillar B Condition	✓	Right C Pillar Trim	✓
RHS Pillar C Condition	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Left D pillar	✓		
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓
Transmission Operation	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel Condition: Faded	⚠	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			

Suspension



Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



OBD Connector



Music System



Lights

Lights



Headlight

Left: Low Brightness lamps



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



AC Heater Operation Switch



AC Blower Switch



Rear Blower Switch



AC Wind Direction



Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisors	✓
Sunvisor	✓	Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	!
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration	!	Door Hinge Condition	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE