



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 NISSAN PATHFINDER

SL | 108,572 KM

VIN: 5N1AR2MM3FC621934

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort









Power driver seat, Memory Seats




Basic Details

 Kilometers	108572	 Specs	Yes
 Engine	3.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	5N1AR2MM3FC621934		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Comfort & Convenience</div>				
Panoramic Sunroof		<div></div>	Cruise Control	<div></div>
Memory Seats		<div></div>	Steering Mounted Audio Controls	<div></div>
<div><div></div> Exteriors</div>				
Fog Light Front		<div></div>		
<div><div></div> Safety & Security</div>				

Navigation 	Parking Sensors Rear 
Reverse Camera 	Front Camera 
Side Camera 	
 Entertainment	
USB Charging Port 	Infotainment System 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Inner Frame: Scratch < 50mm



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door

Panel: Scratch < 50mm



Rear right door

Inner Frame: Light Scuffing < 80mm



Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm, Repainted



Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm, Dent < 30mm



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Grill Damaged



Hood Condition

Hood



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar

Inner Condition: Fair Use Wear



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar

Light Scuffing < 50mm



Left B Pillar

Condition: Scratch < 50mm



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim

Minor scratch



Right B to C Pillar

Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar

Scratch < 50mm



Running Board Condition

Left Running Board

Front Left Floor Trim: Light Scuffing < 80mm



Right Running Board

Front Right Sill Trim: Light Scuffing < 80mm



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear < 50mm



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror

Body: Scratch < 50mm



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/



Left Rear Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/



Scuff < 80mm	
Right Front Alloy/ Rim	
Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/ Scuff < 50mm	⚠
Spare Alloy/ Rim Condition	✓
Wheel cover	✓
Grill Condition	⚠
Light Scuffing < 50mm	
Window Glass	✓
Panel Condition	
Rear Trunk Panel	
Scratch < 50mm	⚠

Scuff < 80mm	
Right Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	⚠
Antenna	✓
Monogram	✓
Wiper	✓

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Battery		
Battery Terminal & Tightness	✓	
Fuel System		
Fuel Cap	✓	Fuel Tank ✓
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
4*4 Condition (If Applicable)	✓	Transmission Fluid ✓

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Brake Master Cylinder	✓	Brake Disc & Brake Pad ✓

Brake Fluid	✓
Pedals	✓
Suspension	
Shock Absorbers	✓

Electricals, Controls & Lights

Keys		
Master Key	✓	
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Engine Sensors ✓
OBD Connector	✓	Radar (If Equipped) ✓
Navigation System	✓	Music System ✓
Sunroof Operation		
Sunroof	✓	
Lights		
Headlight	✓	Interior Lights ✓
Tail Light Cluster		
Right Tail Lamp: Crack / Fair Use Wear > 5mm	!	Daylight Running Lights ✓
License Plate Light	✓	Fog Lights ✓
Air Conditioning		
AC Cooling	✓	AC Switch ✓

AC System Leaks	!	Center AC Vent	✓
Temp In Running < 14°C			
Front Right AC Vent	!	Heater	✓
Light Scuffing			
Rear Blower Switch	!		
Damage			
Parking Sensors	✓	Rear Defogger	!
		Not Working	
USB Charging Port	✓	Rear Entertainment	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery			
Driver Seat: Minor Leather/ Fabric Damage/ Tear	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim			
Front Left Door: Light Scuffing/ Disfiguration, Damaged	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	!
		Crack	

Right Hand Side Front Tyre		Right Hand Side Rear Tyre Crack	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<75%
RHS Front Tyre	<85%	RHS Rear Tyre	<75%
Spare Tyre	<40%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE