



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 NISSAN PATROL

LE TITANIUM | 68,458 KM

VIN: JN8AY2NY2L9402663

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat, Seat Heaters

Basic Details

 Kilometers	68458	 Specs	Yes
 Engine	5.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	8 Seats	 Number of keys	2 Keys
 VIN number	JN8AY2NY2L9402663		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Steering Mounted Audio Controls		Power Tailgate/ Power Trunk	
Central Armrest			
 Exteriors			
Fog Light Front		Running Lights	



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



ABS



Central Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel Condition: Scratch		Right Quarter Panel	
--	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left B Pillar		RHS Pillar B Condition	
---------------	---	------------------------	---

RHS Pillar C Condition		Left C Pillar	
------------------------	---	---------------	---

Left D pillar	
---------------	---

Running Board Condition

Left Running Board		Right Running Board Condition: Scratch	
--------------------	---	---	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Wheel cover



Grill Condition

Scratch



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Exterior Scratch



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Radar (If Equipped)	✓
Music System	✓	Bluetooth Operations	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Lights	✓	Running lights	✓

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓







Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Sunvisors	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim	✓	Door Hinge Condition	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓



Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<90%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE