



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 MERCEDES BENZ CLS 63

AMG | 35,188 KM

VIN: WDDLJ7GB5EA121432

Car highlights



Power packed

Engine size of 5.5 Litres & 8.0 cylinders



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat, Memory Seats & more



Basic Details

 Kilometers	35188	 Specs	Yes
 Engine	5.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	4 Seats	 Number of keys	1 Keys
 VIN number	WDDLJ7GB5EA121432		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Central Armrest	
Remote Engine Start			
 Safety & Security			

Parking Sensors Front	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
ABS	✓	Central Locking	✓
 Exteriors			
Running Lights	✓		
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door
Condition: Scratched



Rear right door



Fenders Condition

Left Fender
Condition: Scratched



Right Fender
Right Fender: Scratched



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper
Condition: Misaligned



Rear Bumper Condition

Rear Bumper
Rear Bumper: Scratched



Hood Condition

Hood
Bonnet: Monogram/Logo Faded



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar
Condition: Scratched



Left B Pillar
Condition: Scratched, Faded



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	!	Rear Windshield	!
Condition: Beading Missing/Broken		Tail Light High Mount Faded	
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	!	Left Side Mirror	✓
Body: Scratched			
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratched			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Alloy Wheel: Scratched		Alloy Wheel: Scratched	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Alloy Wheel: Scratched		Alloy Wheel: Scratched	
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Drive Axle



Transmission Operation



Steering, Suspension & Brakes

Steering

Steering wheel

Condition: Trim Faded



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



Electricals, Controls & Lights

Keys

Master Key



Remote Key Operations

Keyless/ Remote Start



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Controls	✓	Cruise Control	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓	Bluetooth Operations	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Lights	✓	Running lights	✓
Headlight			
Left: Faded	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: AC Vent Broken, Knob Scratched, Instrument Cluster Glass Scratched



Central Console

Condition: Gear Lever Knob Scratched, Trim Scratched



Cup Holder	✓	Sunvisors	✓
Seat Upholstery			
Driver Seat: Depressed/Pressure Mark, Magazine Holder Loose, Scratched, Seat Massage Not Working	!	Manual Seat Movement Driver Seat: Seat Adjuster Lever Broken	!
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Button Faded, Scratched	!
Door Hinge Condition	✓	Carpet	✓
Headliner			
Headliner condition: Vanity Mirror Missing/Broken	!	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE