



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MAZDA CX 5

GTX | 130,743 KM

VIN: JM8KE4W32H0384816

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort









Power driver seat

Basic Details

 Kilometers	130743	 Specs	Yes
 Engine	2.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM8KE4W32H0384816		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Steering Mounted Audio Controls		Central Armrest	
Remote Engine Start			
 Exteriors			
Fog Light Front			



Safety & Security

Lane Departure Warning System



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



ABS



Central Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door
Condition: Faded, Scratched



Rear right door
Condition: Scratched



Fenders Condition

Left Fender
Condition: Dented, Scratched



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk condition

Trunk



Pillars Condition

Left A Pillar
Condition: Scratched



Right A Pillar
Condition: Scratched



Left B Pillar



RHS Pillar B Condition
Scratched



RHS Pillar C Condition




Left C Pillar



Left D pillar



Running Board Condition

Left Running Board Condition: Scratched		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor Condition: Scratched		Firewall Condition	
Head Light Support Condition			
No structural damage			
Chassis Condition		Upper Cross Member Condition	
Lower Cross Member Condition		Chassis Condition	
Radiator Support			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror Body: Scratched		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim Alloy Wheel: Scratched		Right Rear Alloy/ Rim	
Grill Condition		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel Scratched			

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering

Steering wheel Condition: Logo Faded	!	Shock absorbers	✓
---	---	-----------------	---

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
---------------	---	-----------------------	---

Brake Fluid	✓
-------------	---

Suspension

Suspension	✓
------------	---

Electricals, Controls & Lights

Keys

Master Key	✓
------------	---

Remote Key Operations

Keyless/ Remote Start	✓
-----------------------	---

Door Locks

Central Locking Operation	✓	Child Safety Locking	✓
---------------------------	---	----------------------	---

Dashboard

Instrument Panel	✓
------------------	---








Controls	✓	Cruise Control	✓
----------	---	----------------	---

Radar (If Equipped)	✓	Music System	✓
---------------------	---	--------------	---


Bluetooth Operations	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Lights	✓	Headlight Left: Scratched	⚠
Interior Lights	✓	Tail Light Cluster	✓
Turn Signal Lights	✓	License Plate Light	✓
Back Up Light	✓	Fog Lights	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Gear Knob Scratched	⚠
Cup Holder	✓	Sunvisors	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓

Head Rest		Door Controls And Trim	
Door Hinge Condition		Carpet	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE