



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 MERCEDES BENZ GL 500

AMG | 74,426 KM

VIN: WDCDF7DE3FA443822

Car highlights



Power packed

Engine size of 4.6 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat, Memory Seats & more



Basic Details

 Kilometers	74426	 Specs	Yes
 Engine	4.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	WDCDF7DE3FA443822		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Central Armrest	
Remote Engine Start			
 Safety & Security			

Parking Sensors Front	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Front Camera	✓
ABS	✓	Central Locking	✓
 Exteriors			
Running Lights	✓		
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓		





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Condition: Beading Faded, Scratched		Condition: Scratched	
Rear left door		Rear right door	
Condition: Scratched		Condition: Scratched	

Fenders Condition

Left Fender		Right Fender	
Condition: Scratched		Right Fender: Scratched	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratched		Condition: Scratched, Dented, Scratched	


Front Bumper Condition

Front Bumper	
Condition: Misaligned	

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched	








Hood Condition

Hood	
Bonnet: Scratched, Dented	

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Left B Pillar		RHS Pillar B Condition	
		Scratched	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

Running Board Condition			
Left Running Board	✓	Right Running Board Condition: Scratched	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Condition: Beading Missing/Broken	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor Condition: Stained	!	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top Cowl Vent Panel Broken	!		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	!	Window Glass	✓
Chrome Fade			
Wiper	✓		
Panel Condition			
Rear Trunk Panel Trim Lock Missing/Broken	!		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Drive Axle



Transmission Operation



Steering, Suspension & Brakes

Steering

Steering wheel

Condition: Trim Faded, Logo Faded



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



Electricals, Controls & Lights

Keys

Master Key



Remote Key Operations

Keyless/ Remote Start



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Controls	✓	Cruise Control	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓	Bluetooth Operations	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Lights	✓	Running lights	✓
Headlight		Interior Lights	✓
Left: Faded, Washer Not Working	!		
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Rear Entertainment	!
		Rear Seat LCD: Display Scratched	
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	!	Central Console	!
Dashboard And Instrument Panel: Knob		Condition: Trim Scratched, Cover Broken, AC	

Faded		Vent Broken, Sliding Pad Knob Missing	
Cup Holder	✓	Sunvisors	✓
Seat Upholstery			
Driver Seat: Depressed/Pressure Mark, Scratched	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	
		Front Left Door: Button Faded	!
Door Hinge Condition	✓	Carpet	!
		Rear Floor Carpet: Mat Missing	
Headliner			
Headliner condition: Torn/Dirty	!	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE