



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 AUDI A8**

**55 TFSI | 41,956 KM**

VIN: WAUZZZF85KN007429

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat, Memory Seats & more

Basic Details

|  |                   |   |                     |
|--|-------------------|---|---------------------|
|  Kilometers       | 41956             |  Specs             | Yes                 |
|  Engine           | 3.0L              |  Option Type       | Fully Loaded        |
|  Transmission     | Automatic         |  Drive             | All Wheel Drive     |
|  Body Type        | SEDAN             |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | WAUZZZF85KN007429 |   |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Panoramic Sunroof  |  | Cruise Control                  |  |
| Memory Seats   |  | Steering Mounted Audio Controls |  |
| Power Tailgate/ Power Trunk  |  | Central Armrest                 |  |
| Remote Engine Start  |  |                                 |   |
|  <b>Exteriors</b>                 |   |                                 |   |

|  |   |                   |   |
|--|---|-------------------|---|
| Fog Light Front  | ✓ | Running Lights    | ✓ |
|  <b>Safety &amp; Security</b> |   |                   |   |
| Parking Sensors Front  | ✓ | Navigation        | ✓ |
| Parking Sensors Rear   | ✓ | Reverse Camera    | ✓ |
| Blind Spot Monitor   | ✓ | Front Camera      | ✓ |
| Side Camera  | ✓ | ABS               | ✓ |
| Central Locking  | ✓ |                   |   |
|  <b>Entertainment</b>         |   |                   |   |
| Bluetooth Player   | ✓ | USB Charging Port | ✓ |
| Infotainment System  | ✓ |                   |   |





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                      |   |                      |   |
|----------------------|---|----------------------|---|
| Front left door      |  | Front right door     |  |
|                      |   | Condition: Scratched |   |
| Rear left door       |  | Rear right door      |  |
| Condition: Scratched |   | Condition: Scratched |   |

### Fenders Condition

|             |   |                         |   |
|-------------|---|-------------------------|---|
| Left Fender |  | Right Fender            |  |
|             |   | Right Fender: Scratched |   |

### Quarter Panels Condition

|                    |  |                     |  |
|--------------------|--|---------------------|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|--|---------------------|--|

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|             |   |
|-------------|---|
| Rear Bumper |  |
|-------------|---|








### Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Pillars Condition

|                        |   |                        |   |
|------------------------|---|------------------------|---|
| Left A Pillar          |  | Right A Pillar         |  |
| Left B Pillar          |  | RHS Pillar B Condition |  |
| RHS Pillar C Condition |  | Left C Pillar          |  |
| Left D pillar          |  |                        |   |

### Running Board Condition

|                    |   |                     |   |
|--------------------|---|---------------------|---|
| Left Running Board |  | Right Running Board |  |
|--------------------|---|---------------------|---|

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Alloy Wheel: Scratched



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Engine Oil (Condition & Level) | ✓ | Exhaust System         | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition     | ✓ |
| Radiator Coolant               | ✓ |                        |   |
| Battery                        |   |                        |   |
| Battery Terminal & Tightness   | ✓ |                        |   |
| Transmission Operation         |   |                        |   |
| Drive Axle                     | ✓ | Transmission Operation | ✓ |

## **Steering, Suspension & Brakes**

|                |   |                       |   |
|----------------|---|-----------------------|---|
| Steering       |   |                       |   |
| Steering wheel | ✓ | Shock absorbers       | ✓ |
| Brake System   |   |                       |   |
| Parking Brake  | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid    | ✓ |                       |   |
| Suspension     |   |                       |   |
| Suspension     | ✓ |                       |   |

## **Electricals, Controls & Lights**

|                           |   |                      |   |
|---------------------------|---|----------------------|---|
| Keys                      |   |                      |   |
| Master Key                | ✓ |                      |   |
| Remote Key Operations     |   |                      |   |
| Keyless/ Remote Start     | ✓ |                      |   |
| Door Locks                |   |                      |   |
| Central Locking Operation | ✓ | Child Safety Locking | ✓ |
| Dashboard                 |   |                      |   |
| Instrument Panel          | ✓ |                      |   |
| Controls                  | ✓ | Cruise Control       | ✓ |
| Radar (If Equipped)       | ✓ | Navigation System    | ✓ |
| Music System              | ✓ | Bluetooth Operations | ✓ |

## Sunroof Operation

Sunroof



## Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



## Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Seat Heaters



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Sunvisors



Seat Upholstery

Driver Seat: Depressed/Pressure Mark



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim





Door Hinge Condition



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<85%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE