



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN SENTRA

S | 89,244 KM

VIN: MNTBB7A92K6059858

Car highlights



Great Parking Assistance

Parking Sensors Rear



Music System

Enjoy your drive with music system



Central Arm Rest
















Central arm rest for extra comfort



Tilt Steering wheel








Tilt steering wheel for extra comfort

Basic Details

 Kilometers	89244	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MNTBB7A92K6059858		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Safety & Security</div>			
Parking Sensors Rear	<div></div>	ABS	<div></div>
Central Locking	<div></div>		
<div><div></div> Comfort & Convenience</div>			
Central Armrest	<div></div>		
<div><div></div> Entertainment</div>			

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Condition: Scratched



Rear left door

Condition: Scratched



Rear right door

Condition: Beading Missing/Broken



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board

Condition: Scratched



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Transmission Operation



Steering, Suspension & Brakes

Steering

Steering wheel



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Radar (If Equipped)



Music System



Lights

Lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Scratched	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery Driver Seat: Stained	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		



Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%

RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<90%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE