



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 BMW 750LI**

**EXECUTIVE | 32,360 KM**

VIN: WBA7F2A03KB236279

## Car highlights



### **Power packed**

Engine size of 4.4 Litres & 8.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat, Memory Seats & more

## Basic Details

 Kilometers	<b>32360</b>	 Specs	<b>Yes</b>
 Engine	<b>4.4L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>3 Keys</b>
 VIN number	<b>WBA7F2A03KB236279</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Sliding Doors		Heads up Display	
Power Tailgate/ Power Trunk		Central Armrest	
Remote Engine Start			



## Exteriors

Fog Light Front



Running Lights



## Safety & Security

Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Front Camera



ABS



Central Locking



## Entertainment

Bluetooth Player



USB Charging Port



Infotainment System







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Condition: Scratched	
Rear left door		Rear right door Condition: Scratched	

Power Sliding Doors 

### Fenders Condition

Left Fender		Right Fender Condition: Scratched	
-------------	---	--------------------------------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Scratched	
--------------------	---	---	---

### Front Bumper Condition

Front Bumper  
Condition: Scratched 

### Rear Bumper Condition

Rear Bumper 


### Hood Condition

Hood 

### Trunk conditon

Trunk 

### Pillars Condition

Left A Pillar  Right A Pillar 

Left B Pillar  RHS Pillar B Condition 

RHS Pillar C Condition  Left C Pillar 

Left D pillar 

Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Condition



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Scratched



Left Side Mirror



Right Side Mirror

Body: Scratched



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

---

## **Steering, Suspension & Brakes**

### Steering

Steering wheel	✓	Shock absorbers	✓
----------------	---	-----------------	---

### Brake System

Parking Brake	✓	Brake Master Cylinder	✓
---------------	---	-----------------------	---

Brake Fluid	✓		
-------------	---	--	--

### Suspension

Suspension	✓		
------------	---	--	--

---

## **Electricals, Controls & Lights**

### Keys

Master Key	✓		
------------	---	--	--

### Remote Key Operations

Keyless/ Remote Start	✓		
-----------------------	---	--	--

### Door Locks

Central Locking Operation	✓	Child Safety Locking	✓
---------------------------	---	----------------------	---

### Dashboard

Instrument Panel	✓		
------------------	---	--	--

Controls	✓	Cruise Control	✓
----------	---	----------------	---

Heads Up Display	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Bluetooth Operations	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Rear Entertainment			
Rear Seat LCD: Headphone Missing	!	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Loose	!
--------------------------------	---	-------------------------------------	---



Cup Holder		Sunvisors	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Seat Belt with issues	
Head Rest		Door Controls And Trim	
Door Hinge Condition		Carpet	
Headliner		Rear View Mirror	
Toolkit			

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	No spare tyre		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE