



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 MERCEDES BENZ E 300

PREMIUM | 31,189 KM

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat, Memory Seats & more

## Basic Details

 Kilometers	<b>31189</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>9 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>W1KZF8DB6LA862207</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Lane Departure Warning System	
Parking Sensors Front		Parking Sensors Rear	
Auto Park Assist		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Traction Control		Front Camera	

Side Camera	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		



### Comfort & Convenience

Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Rear Armrest with cupholder	✓
Steering Mounted Audio Controls	✓	Power Folding Mirrors	✓
Power Head Rest	✓	Rear Defogger	✓
Central Armrest	✓	Automatic Headlights	✓
Steering Column Adjuster	✓		



### Performance

Paddle Shift	✓		
--------------	---	--	--



### Exteriors

Running Lights	✓	LED Headlights	✓
----------------	---	----------------	---



### Entertainment

Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Condition: Scratched

Front right door



Rear left door



Condition: Scratched

Rear right door



Panel: Low Visual Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
RHS Pillar B Condition	✓	Right C Pillar Trim	✓
RHS Pillar C Condition	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Left D pillar	✓		
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

---

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓
Transmission Operation	✓		

---

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Suspension	✓	Shock Absorbers	✓

---

## Electricals, Controls & Lights

## Keys

Master Key		Spare Key(s)	
------------	--	--------------	--

## Door Locks

Child Safety Locking	
----------------------	--

## Dashboard

Instrument Panel	
------------------	--

## Airbags

Airbags	
---------	--

Controls		Cruise Control	
----------	--	----------------	--

Heads Up Display		Infotainment Display	
------------------	--	----------------------	--

OBD Connector		Radar (If Equipped)	
---------------	--	---------------------	--

Navigation System		Music System	
-------------------	--	--------------	--

Condition: Available - SD Card Missing			
--	--	--	--

Bluetooth Operations	
----------------------	--

Sunroof Operation	
-------------------	--

Sunroof	
---------	--

Camera	
--------	--

Lights	
--------	--

Lights		Running lights	
--------	--	----------------	--

Headlight		Interior Lights	
-----------	--	-----------------	--

Tail Light Cluster		Turn Signal Lights	
--------------------	--	--------------------	--

Daylight Running Lights		License Plate Light	
-------------------------	--	---------------------	--

Back Up Light		Trunk Lid Release/Trunk Lid Light Operation	
---------------	--	---	--

Air Conditioning	
------------------	--

AC Air Direction Switch		Blower Motor	
-------------------------	--	--------------	--

Compressor		Condenser	
------------	--	-----------	--

AC Cooling		AC Switch	
------------	--	-----------	--

AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
Rear Blower Switch	✓	AC Wind Direction	✓
Rear Left AC Vent	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

---

## **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisors	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim	✓	Door Hinge Condition	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

---

## **Tyres**

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Life remaining

LHS Front Tyre <75% LHS Rear Tyre <55%

RHS Front Tyre <75% RHS Rear Tyre <55%

Spare Tyre  
No spare  
tyre



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE