



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2014 BMW X5**

**XDRIVE50I | 82,759 KM**

VIN: WBAKR6102E0G96836

## Car highlights



### **Power packed**

Engine size of 4.4 Litres & 8.0 cylinders



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat, Memory Seats & more















## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>82759</b>             |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>4.4L</b>              |  Option Type       | <b>Full Option</b>          |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>All Wheel Drive</b>      |
|  Body Type        | <b>SUV</b>               |  Fuel              | <b>Petrol</b>               |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Black</b> |
|  Interior Trim    | <b>Leather Trim</b>      |  Number of Airbags | <b>6 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>1 Keys</b>               |
|  VIN number      | <b>WBAKR6102E0G96836</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  <b>Comfort &amp; Convenience</b> |   |
|--|---|
| Panoramic Sunroof                 | Cruise Control                   |
| Memory Seats                      | Steering Mounted Audio Controls  |
| Heads up Display                  | Power Tailgate/ Power Trunk      |
| Central Armrest                   | Remote Engine Start              |
|  <b>Exteriors</b>                 |   |

|  |   |                   |   |
|--|---|-------------------|---|
| Fog Light Front  |   | Running Lights    |   |
|  <b>Safety &amp; Security</b> |   |                   |   |
| Parking Sensors Front  |  | Navigation        |  |
| Parking Sensors Rear   |  | Reverse Camera    |  |
| Front Camera   |  | ABS               |  |
| Central Locking  |  |                   |   |
|  <b>Entertainment</b>         |   |                   |   |
| Bluetooth Player   |  | USB Charging Port |  |
| Infotainment System  |  |                   |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Condition: Scratched, Beading  
Missing/Broken



Front right door



Rear left door



Rear right door

Condition: Scratched



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel

Condition: Scratched



Right Quarter Panel

Condition: Scratched



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood

Bonnet: Scratched



### Trunk condition

Trunk



### Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



### Running Board Condition

|   |   |                              |   |
|---|---|------------------------------|---|
| Left Running Board<br>Condition: Scratched            | ⚠ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped)                 |   |                              |   |
| Sun Roof Glass  | ✓ |                              |   |
| Windshield Condition                                  |   |                              |   |
| Front Windshield<br>Condition: Beading Missing/Broken | ⚠ | Rear Windshield              | ✓ |
| Structural Assessment                                 |   |                              |   |
| Chassis Condition                                     | ✓ | Apron                        | ✓ |
| Boot Floor  | ✓ | Firewall Condition           | ✓ |
| Head Light Support Condition                          | ✓ |                              |   |
| No structural damage                                  |   |                              |   |
| Chassis Condition                                     | ✓ | Upper Cross Member Condition | ✓ |
| Lower Cross Member Condition                          | ✓ | Chassis Condition            | ✓ |
| Radiator Support                                      | ✓ |                              |   |
| Cowl Top  |   |                              |   |
| Cowl Top  | ✓ |                              |   |
| Rear View Mirror Condition                            |   |                              |   |
| Left Hand Side Mirror                                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror<br>Body: Scratched                  | ⚠ | Right Hand Side Mirror       | ✓ |
| Alloy Wheel/ Rim                                      |   |                              |   |
| Left Front Alloy/ Rim                                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Grill Condition                                       | ✓ | Window Glass                 | ✓ |
| Wiper   | ✓ |                              |   |
| Panel Condition                                       |   |                              |   |
| Rear Trunk Panel<br>Scratched                         | ⚠ |                              |   |

## Engine

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Engine Body                    | ✓ | Engine Performance     | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System         | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition     | ✓ |
| Radiator Coolant               | ✓ |                        |   |
| Battery                        |   |                        |   |
| Battery Terminal & Tightness   | ✓ |                        |   |
| Transmission Operation         |   |                        |   |
| Drive Axle                     | ✓ | Transmission Operation | ✓ |

---

## **Steering, Suspension & Brakes**

### Steering

|                |   |                 |   |
|----------------|---|-----------------|---|
| Steering wheel | ✓ | Shock absorbers | ✓ |
|----------------|---|-----------------|---|

### Brake System

|               |   |                       |   |
|---------------|---|-----------------------|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
|---------------|---|-----------------------|---|

|             |   |  |  |
|-------------|---|--|--|
| Brake Fluid | ✓ |  |  |
|-------------|---|--|--|

### Suspension

|            |   |  |  |
|------------|---|--|--|
| Suspension | ✓ |  |  |
|------------|---|--|--|

---

## **Electricals, Controls & Lights**

### Keys

|            |   |  |  |
|------------|---|--|--|
| Master Key | ✓ |  |  |
|------------|---|--|--|

### Remote Key Operations

|                       |   |  |  |
|-----------------------|---|--|--|
| Keyless/ Remote Start | ✓ |  |  |
|-----------------------|---|--|--|

### Door Locks

|                           |   |                      |   |
|---------------------------|---|----------------------|---|
| Central Locking Operation | ✓ | Child Safety Locking | ✓ |
|---------------------------|---|----------------------|---|

### Dashboard

|                  |   |  |  |
|------------------|---|--|--|
| Instrument Panel | ✓ |  |  |
|------------------|---|--|--|

|          |   |                |   |
|----------|---|----------------|---|
| Controls | ✓ | Cruise Control | ✓ |
|----------|---|----------------|---|

|                            |   |   |   |
|----------------------------|---|---|---|
| Heads Up Display           | ✓ | Radar (If Equipped)                         | ✓ |
| Navigation System          | ✓ | Music System                                | ✓ |
| Bluetooth Operations       | ✓ |   |   |
| Sunroof Operation          |   |   |   |
| Sunroof                    | ✓ |   |   |
| Camera                     | ✓ |   |   |
| Lights                     |   |   |   |
| Lights                     | ✓ | Running lights                              | ✓ |
| Headlight                  |   | Interior Lights                             | ✓ |
| Left: Washer Not Working   | ! | Turn Signal Lights                          | ✓ |
| Tail Light Cluster         | ✓ | Back Up Light                               | ✓ |
| License Plate Light        | ✓ | Trunk Lid Release/Trunk Lid Light Operation | ✓ |
| Fog Lights                 | ✓ |   |   |
| Air Conditioning           |   |   |   |
| AC Air Direction Switch    | ✓ | Blower Motor                                | ✓ |
| Compressor                 | ✓ | Condenser                                   | ✓ |
| AC Cooling                 | ✓ | AC Switch                                   | ✓ |
| AC System Leaks            | ✓ | Heater                                      | ✓ |
| AC Heater Operation Switch | ✓ | AC Blower Switch                            | ✓ |
| AC Wind Direction          | ✓ |   |   |
| Rear Defogger              | ✓ | USB Charging Port                           | ✓ |
| Power/ Manual Windows      | ✓ | Seat Heaters                                | ✓ |
| Memory Seats               | ✓ |   |   |

## Interiors & Luggage

|  |   |                          |   |
|--|---|--------------------------|---|
| Dashboard And Instrument Panel             |   | Central Console          |   |
| Dashboard And Instrument Panel: Knob Faded | ! | Condition: Cover Missing | ! |



|   |  |                        |  |
|---|--|------------------------|--|
| Cup Holder  |  | Sunvisors              |  |
| Seat Upholstery<br>Driver Seat: Depressed/Pressure Mark |  | Manual Seat Movement   |  |
| Seat Belts  |  | Seat Belt with issues  |  |
| Head Rest   |  | Door Controls And Trim |  |
| Door Hinge Condition                                    |  | Carpet                 |  |
| Headliner   |  | Rear View Mirror       |  |
| Toolkit   |  |                        |  |

## Tyres

### Tyres Condition

|                            |                  |                           |      |
|----------------------------|------------------|---------------------------|------|
| Left Hand Side Front Tyre  |                  | Left Hand Side Rear Tyre  |      |
| Right Hand Side Front Tyre |                  | Right Hand Side Rear Tyre |      |
| Tyres Depth (Remaining)    |                  |                           |      |
| LHS Front Tyre             | <75%             | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <75%             | RHS Rear Tyre             | <75% |
| Spare Tyre                 | No spare<br>tyre |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE