



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 BMW 640i

M SPORT | 59,464 KM

VIN: WBA6D010XJGA01792

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth














Enjoy your drive with bluetooth



Amazing Comfort













Power driver seat, Memory Seats

Basic Details

 Kilometers	59464	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Seating Capacity	4 Seats
 VIN number	WBA6D010XJGA01792		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Moonroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Heads up Display		Power Tailgate/ Power Trunk	
Central Armrest		Remote Engine Start	
 Exteriors			
Fog Light Front		Running Lights	



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Front Camera



Side Camera



ABS



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Condition: Scratched



Rear left door



Rear right door

Condition: Scratched



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Scratched



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Scratched



Hood Condition

Hood



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Condition	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

 **Engine & Transmission**

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Turbocharger/ Supercharger	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Remote Key Operations			
Keyless/ Remote Start	✓		
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Heads Up Display	✓
Music System	✓	Bluetooth Operations	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Lights	✓	Running lights	✓
Headlight	✓	Interior Lights	✓

Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Scratched	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery Driver Seat: Scratched	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Scratched	!
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<90%

LHS Rear Tyre

<65%

RHS Front Tyre

<90%

RHS Rear Tyre

<65%

Spare Tyre

No spare

tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE