



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 CHEVROLET MALIBU

LS | 80,831 KM

VIN: KL1GD5CU7GB500287

Car highlights



Running Lights

This car has a Running lights



Music System

Enjoy your drive with music system



Amazing Comfort
















Power driver seat



Central Arm Rest








Central arm rest for extra comfort

Basic Details

 Kilometers	80831	 Specs	Yes
 Engine	2.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KL1GD5CU7GB500287		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Running Lights	
 Comfort & Convenience	
Central Armrest	
 Safety & Security	
ABS	
	Central Locking 



Entertainment

Infotainment System







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Condition: Scratched		Condition: Faded, Scratched	
Rear left door		Rear right door	
		Condition: Faded	

Fenders Condition

Left Fender		Right Fender	
		Right Fender: Scratched	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Scratched	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---








Hood Condition

Hood	
------	---

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Left B Pillar		RHS Pillar B Condition	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

Running Board Condition

Left Running Board	⚠	Right Running Board	⚠
Condition: Scratched		Condition: Scratched	
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	⚠		
Cowl Vent Panel Broken			
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Right Rear Alloy/ Rim	✓		
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body			
Mount Condition: Engine Mount Cover Missing	⚠	Engine Performance	✓
Engine Oil (Condition & Level)	⚠	Exhaust System	✓

Leakage From Seal			
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel			
Condition: Trim Scratched	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Music System	✓		
Lights			
Lights	✓	Running lights	✓
Headlight			
Left: Faded	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓

Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Condition: Trim Scratched, Gear Knob Scratched



Cup Holder



Sunvisors



Seat Upholstery



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim

Rear Right Door: Scratched



Door Hinge Condition



Carpet



Headliner



Rear View Mirror

Broken



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre	<div><div></div><div>✓</div></div>		
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE