



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 FORD EXPLORER
BASE AWD | 101,003 KM

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort









Power driver seat









Basic Details

 Kilometers	101003	 Specs	Yes
 Engine	3.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1FM5K8B86HGA91159		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Central Armrest			
 Exteriors			
Fog Light Front		Running Lights	
 Safety & Security			

Parking Sensors Rear		Reverse Camera	
ABS		Central Locking	
 Entertainment			
Bluetooth Player		USB Charging Port	
Infotainment System			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Beading Missing/Broken



Front right door



Rear left door
Condition: Beading Missing/Broken



Rear right door
Condition: Scratched, Beading
Missing/Broken



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper
Condition: Scratched



Rear Bumper Condition

Rear Bumper
Rear Bumper: Faded



Hood Condition

Hood



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar	✓		
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield Condition: Beading Missing/Broken	!	Rear Windshield	✓
Structural Assessment			
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Head Light Support Condition	✓
No structural damage			
Chassis Condition	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Radiator Support	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Scratched	!	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim Alloy Wheel: Scratched	!
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition Chrome Chipped	!	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratched	!		

Engine & Transmission

Engine			
Engine Body	!	Engine Performance	✓

Damage & Leaks: Engine Oil Leakage From Tappet Cover

Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Drive Axle



Transmission Operation



Steering, Suspension & Brakes

Steering

Steering wheel



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Cruise Control



Music System



Bluetooth Operations



Camera



Lights

Lights



Running lights



Headlight



Interior Lights



Left: Scratched

Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Trim
Scratched, Trim Broken



Central Console

Condition: Gear Knob Scratched



Cup Holder



Sunvisors



Seat Upholstery

Driver Seat: Stained



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim



Door Hinge Condition



Carpet

Rear Floor Carpet: Missing/Torn



Headliner

Headliner condition: Torn/Dirty



Rear View Mirror



Toolkit

Luggage Compartment: Scratched



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE