



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 CHEVROLET CAMARO

CALLAWAY SC630 | 23,539 KM

VIN: 1G1F91R70H0170451

Car highlights



Power packed

Engine size of 6.2 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat, Memory Seats & more












Basic Details

 Kilometers	23539	 Specs	Yes
 Engine	6.2L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	COUPE	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	4 Seats	 Number of keys	2 Keys
 VIN number	1G1F91R70H0170451		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Heads up Display		Power Tailgate/ Power Trunk	
Central Armrest		Remote Engine Start	
 Safety & Security			

Navigation		Parking Sensors Rear	
Reverse Camera		ABS	
Central Locking			
 Exteriors			
Running Lights			
 Entertainment			
Bluetooth Player		USB Charging Port	
Infotainment System			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Condition: Scratched



Rear left door



Rear right door



Fenders Condition

Left Fender

Condition: Scratched



Right Fender

Right Fender: Scratched



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper

Condition: Scratched



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Scratched



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Alloy Wheel: Scratched



Left Rear Alloy/ Rim



Right Front Alloy/ Rim

Alloy Wheel: Scratched



Right Rear Alloy/ Rim

Alloy Wheel: Scratched



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



 **Engine & Transmission**

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel		Shock absorbers	✓
Condition: Trim Scratched	⚠		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Remote Key Operations			
Keyless/ Remote Start	✓		
Door Locks			
Central Locking Operation	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Navigation System	✓

Music System	✓	Bluetooth Operations	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Lights	✓	Running lights	✓
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

 **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Sunvisors	✓
Seat Upholstery Driver Seat: Scratched	⚠	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓

Head Rest		Door Controls And Trim	
Door Hinge Condition		Carpet Front floor carpet: Missing/Torn	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	

Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE