



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 INFINITI QX60

PREMIUM | 95,380 KM

VIN: 5N1DL0MM7JC520004

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Music System














Enjoy your drive with music system



Amazing Comfort









Power driver seat, Memory Seats

Basic Details

 Kilometers	95380	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	5N1DL0MM7JC520004		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
 Exteriors			
Fog Light Front			
 Safety & Security			

Parking Sensors Front		Navigation	
Parking Sensors Rear		Reverse Camera	
Front Camera		Side Camera	
 Entertainment			
USB Charging Port		Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Rear left door

Handle: Scratch < 50mm



Rear right door

Handle: Scratch < 50mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Scratch < 50mm



Right Fender

Right Fender: Scratch < 50mm, Paint Chip-off < 5mm 


Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm 

Front Bumper Condition

Front Bumper

Condition: Misaligned



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip < 8mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Beading: Misaligned	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Paint Chip-off < 5mm	⚠	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Scratches	⚠	Left Rear Alloy/ Rim Rim: Scratch	⚠
Right Front Alloy/ Rim Rim: Scratch	⚠	Right Rear Alloy/ Rim Rim: Scratch	⚠

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel Paint Chip Off < 5mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Performance	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Brake Calipers	✓		

Pedals 

Suspension

Shock Absorbers 

 **Electricals, Controls & Lights**

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Navigation System 


Music System 

Sunroof Operation


Sunroof 


Camera 

Lights

Headlight
Left: Light Scuff Marks < 50mm 

Interior Lights 

Tail Light Cluster
Left Tail Lamp: 1. Trunk tail lamp LHS minor gap 

Turn Signal Lights
Left ORVM: Light Scuffing < 50mm 

Daylight Running Lights 

License Plate Light 

Fog Lights 

Air Conditioning

AC Air Direction Switch	✓	AC Cooling	✓
AC Display	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel			
Interior Dashboard Upholstery: Scuffing<50mm	!	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel		Sunvisor	✓
Steering Wheel Fair Use Wear	!		
Seat Upholstery		Manual Seat Movement	✓
Rear Left Seat: Minor Fair Use Wear/ Color Dullness, Minor Leather/ Fabric Damage/ Tear	!		
Seat Belts	✓	Head Rest	✓
Door Controls And Trim		Grab Handle	✓
Front Left Door: Scuffing>80mm, Stain	!		
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE