



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 RENAULT CAPTUR

PE | 93,672 KM

VIN: VF12RRHE9FW527073

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Music System
















Enjoy your drive with music system



Tilt Steering wheel









Tilt steering wheel for extra comfort

Basic Details

 Kilometers	93672	 Specs	Yes
 Engine	1.2L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	VF12RRHE9FW527073		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Remote Engine Start			
 Safety & Security			
Parking Sensors Rear		ABS	
Central Locking			



Exteriors

Running Lights



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Condition: Scratched, Beading
Missing/Broken



Front right door

Condition: Scratched



Rear left door

Condition: Scratched



Rear right door

Condition: Scratched



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper

Condition: Dented



Rear Bumper Condition

Rear Bumper

Rear Bumper: Scratched



Hood Condition

Hood



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar

Condition: Scratched



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar
Scratched



Left D pillar



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield

Condition: Spots, Broken



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Wheel cover



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratched



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness 

Transmission Operation

Transmission Operation 

Steering, Suspension & Brakes

Steering

Steering wheel 

Shock absorbers 

Brake System

Parking Brake 

Brake Master Cylinder 

Brake Fluid 

Suspension

Suspension 

Electricals, Controls & Lights

Keys

Master Key 

Remote Key Operations

Keyless/ Remote Start 

Door Locks

Central Locking Operation 

Child Safety Locking 

Dashboard

Instrument Panel 

Controls 

Cruise Control 

Music System 

Lights

Lights 

Running lights 

Headlight 

Interior Lights 

Tail Light Cluster 

Turn Signal Lights 

License Plate Light 

Back Up Light 




Fog Lights	⚠	Trunk Lid Release/Trunk Lid Light Operation	✓
Right Fog Light: Cover Broken			
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	⚠	Central Console	⚠
Dashboard And Instrument Panel: Scratched		Condition: Stained	
Cup Holder	✓	Sunvisors	✓
Seat Upholstery	⚠	Manual Seat Movement	✓
Passenger Seat: Stained			
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner	⚠	Rear View Mirror	✓
Headliner condition: Torn/Dirty			
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE