



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 TOYOTA CAMRY

S | 96,079 KM

VIN: JTNBF9HK4K3026115

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Music System
















Enjoy your drive with music system



Central Arm Rest









Central arm rest for extra comfort

Basic Details

 Kilometers	96079	 Specs	Yes
 Engine	2.5L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JTNBF9HK4K3026115		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Central Armrest			
 Safety & Security			
Parking Sensors Rear		ABS	
Central Locking			



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Dented



Rear left door



Rear right door
Condition: Scratched



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel
Condition: Scratched



Right Quarter Panel
Condition: Scratched



Front Bumper Condition

Front Bumper
Condition: Scratched



Rear Bumper Condition

Rear Bumper
Rear Bumper: Scratched



Hood Condition

Hood



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board		Right Running Board Condition: Scratched	
Windshield Condition			
Front Windshield Condition: Scratched		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Head Light Support Condition			
No structural damage			
Chassis Conditon		Upper Cross Member Condition	
Lower Cross Member Condition		Chassis Condition	
Radiator Support			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror Body: Scratched		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Wheel cover		Grill Condition	
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			

Battery Terminal & Tightness 

Transmission Operation

Transmission Operation 

Steering, Suspension & Brakes

Steering

Steering wheel
Condition: Trim Faded 

Shock absorbers 

Brake System

Parking Brake 

Brake Master Cylinder 

Brake Fluid 

Suspension

Suspension 

Electricals, Controls & Lights

Keys

Master Key 

Door Locks

Central Locking Operation 

Child Safety Locking 

Dashboard

Instrument Panel 

Cruise Control 

Music System 

Lights

Lights 

Headlight 

Interior Lights 

Tail Light Cluster
Left Tail Lamp: Scratched 

Turn Signal Lights 

License Plate Light 

Back Up Light 

Trunk Lid Release/Trunk Lid Light Operation 

Air Conditioning

AC Air Direction Switch 

Blower Motor 

Compressor 

Condenser 

AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	⚠	Central Console	⚠
Dashboard And Instrument Panel: Scratched		Condition: Scratched	
Cup Holder	✓	Sunvisors	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	⚠
		Front Left Door: Stained	
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE