



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 ASTON MARTIN VANTAGE**

**V8 S | 40,924 KM**

VIN: SCFEKBDL1FGC19327

## Car highlights



### **Power packed**

Engine size of 4.7 Litres & 8.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat















## Basic Details

 Kilometers	<b>40924</b>	 Specs	<b>Yes</b>
 Engine	<b>4.7L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>COUPE</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>4 Airbags</b>
 Seating Capacity	<b>2 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>SCFEKBDL1FGC19327</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Power Folding Mirrors	
Rear Defogger		Central Armrest	
Automatic Headlights		Steering Column Adjuster	
 <b>Safety &amp; Security</b>			

Navigation		Parking Sensors Front	
Reverse Camera		Traction Control	
Airbag Driver Front		ABS	
Central Locking			
 <b>Performance</b>			
Paddle Shift			
 <b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			
 <b>Exteriors</b>			
HID Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

#### Front left door

Inner Handle: Color/Chrome Dullness



#### Front right door

Condition: Beading Faded, Fabric Torned



### Fenders Condition

#### Left Fender



#### Right Fender

Right Fender: Light Scuffing



### Quarter Panels Condition

#### Left Quarter Panel



#### Right Quarter Panel

Condition: Chip



### Front Bumper Condition

#### Front Bumper



### Rear Bumper Condition

#### Rear Bumper



### Hood Condition

#### Hood



### Trunk Condition

#### Trunk



### Trunk conditon

#### Trunk



### Pillars Condition

#### Left A Pillar



#### Right A Pillar



#### Left A to B Pillar Beading

Beading Crack/ Tear > 5mm



#### Right A to B Pillar Beading



#### Right A to B Pillar



#### Left B Pillar



#### RHS Pillar B Condition



#### RHS Pillar C Condition



Left D pillar			
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
No structural damage			
Chassis Conditon		Upper Cross Member Condition	
Lower Cross Member Condition		Chassis Condition	
Radiator Support			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Body: Scratched			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Wheel cover		Antenna	
Grill Condition		Monogram	
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			

## Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓
Transmission Operation	✓		

## Steering, Suspension & Brakes

### Steering

Steering wheel Condition: Trim Scratched	!	Shock absorbers	✓
---	---	-----------------	---

### Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

### Suspension

Suspension	✓	Shock Absorbers	✓
------------	---	-----------------	---

## Electricals, Controls & Lights

### Keys

Master Key Button Faded	!	Spare Key(s) Buttons Faded	!
----------------------------	---	-------------------------------	---

### Door Locks

Central Locking Operation	✓		
---------------------------	---	--	--

### Dashboard

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Bluetooth Operations	✓	Camera	✓
Lights			
Lights	✓	Headlight Right: Light Scuff Marks < 50mm	!
Interior Lights	✓	Tail Light Cluster	✓
Turn Signal Lights	✓	License Plate Light	✓
Back Up Light	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors			
Rear Sensors: Not Working/ Faulty	!	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Scuffing/ Disfiguration/	!	Box: Minor Crack/Fair Use Wear/ Scuffing	!



Melted

Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisors



Sunvisor



Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off, Minor Leather/ Fabric Fair Use Wear/ Tears



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim



Door Hinge Condition



Carpet

Front floor carpet: Stained



Headliner

Headliner condition: Torn/Dirty



Rear View Mirror



Toolkit

Condition: Missing



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<75%

RHS Rear Tyre

<55%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE