



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 GMC SIERRA

SLE | 18,449 KM

VIN: 3GTN99EF0MG430044

Car highlights



Power packed

Engine size of 5.3 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat











Basic Details

 Kilometers	18449	 Specs	Yes
 Engine	5.3L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	TRUCK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	2 Seats	 Number of keys	2 Keys
 VIN number	3GTN99EF0MG430044		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Central Armrest	
Remote Engine Start			
 Safety & Security			
Parking Sensors Front		Parking Sensors Rear	

Reverse Camera		Blind Spot Monitor	
ABS		Central Locking	
 Exteriors			
Running Lights			
 Entertainment			
Bluetooth Player		USB Charging Port	
Infotainment System			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel
Condition: Scratched



Right Quarter Panel
Condition: Scratched



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood
Bonnet: Scratched



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board
Condition: Scratched



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Condition: Scratched

Head Light Support Condition



No structural damage

Chassis Condition



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Grill Condition



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Drive Axle



Transmission Operation



Steering, Suspension & Brakes

Steering

Steering wheel



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



Electricals, Controls & Lights

Keys

Master Key



Remote Key Operations

Keyless/ Remote Start



Door Locks

Central Locking Operation



Dashboard

Instrument Panel



Controls



Cruise Control



Radar (If Equipped)



Music System



Bluetooth Operations



Camera



Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Scratched	⚠
Cup Holder	✓	Sunvisors	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE