



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 FORD ECOSPORT

AMBIENTE | 86,194 KM

VIN: MAJFK1BA0HAU22250

Car highlights



Music System

Enjoy your drive with music system



Amazing Comfort
















Power driver seat



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

 Kilometers	86194	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MAJFK1BA0HAU22250		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Entertainment

Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Hinge: Door stopper damaged



Front right door

Handle: Faded



Rear left door

Handle: Scratch < 50mm, Faded



Rear right door

Handle: Faded



Fenders Condition

Left Fender

Condition: Dent < 30mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Scratch < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm



Right Quarter Panel

Condition: Paint Chip-off < 5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Colour Mismatch/ Low Brightness



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration < 50mm



Trunk condition

Trunk



Roof Condition

Roof

Roof Moulding Condition: Colour fade



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar Colour Mismatch	!	Left B Pillar Condition: Colour mismatch/Low Brightness	!
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board Condition: Colour Faded	!	Right Running Board Condition: Colour faded	!
--	---	---	---

Windshield Condition

Front Windshield Beading: Mouldings Crack/ Fair Use Wear > 50mm	!	Rear Windshield Light Scuffing < 50mm	!
---	---	---------------------------------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Cowl Top Beading: Crack/Fair Use Wear>50mm	!	Head Light Support Condition	✓
Cowl Top Fair Use Wear/Crack<5mm	!		

Rear View Mirror Condition

Left Hand Side Mirror Body: Faded	!	Left Side Mirror	✓
Right Side Mirror Body: Colour Faded	!	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Face/ Scuff > 50mm, Alloy Edge/ Scuff < 80mm	!

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	!
		Bent/Broken/Fair Use Wear/Missing	
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	!
		Rear Wiper Blade: Faded	
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel

Odometer: Minor scratch



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm, Low

Brightness lamps



Interior Lights



Tail Light Cluster

Right Tail Lamp: Light Scuffing < 50mm



Turn Signal Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	⚠
		Cigarette Lighter: Cigarette Lighter Missing	
Cup Holder	✓	Glove Box	⚠
		Glove Box: Minor scratch	
Steering Wheel	⚠	Sunvisor	⚠
Color Faded		Left: Sunvisor LHS Minor Crack/Fair Use	
		Wear, Sunvisor RHS Minor Crack/Damage	
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks, Minor	⚠		
Fair Wear/Fade off, Minor Cigarette Burn,			
Minor Leather/ Fabric Damage/ Tear			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	⚠	Grab Handle	
Front Left Door: Light Scuffing/ Disfiguration		Front Right: Not Folding/Not Fixed, Fair Use	⚠
		Wear	
Carpet	⚠	Headliner	⚠
Front Right Floor Mat: Smudge/Burn/Crack		Rear Left: Light Scuffing	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	⚠		
Crack/ Uneven Wear			
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<45%
Spare Tyre	<90%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE