



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 GMC YUKON

DENALI | 95,793 KM

VIN: 1GKS27KJ2KR115039

Car highlights



Power packed

Engine size of 6.2 Litres & 8.0 cylinders



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Rear Seat Entertainment
















Enjoy your drive with Rear Seat Entertainment



Amazing Comfort












Power driver seat, Memory Seats & more


Basic Details

 Kilometers	95793	 Specs	Yes
 Engine	6.2L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1GKS27KJ2KR115039		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Heads up Display		Climate Control AC	
Cruise Control		Memory Seats	
Steering Mounted Audio Controls		Power Folding Mirrors	
Ventilated Seat		Power Tailgate/ Power Trunk	
Cool Box		Rear Defogger	

Central Armrest		Remote Engine Start	
Automatic Headlights		Steering Column Adjuster	
 Safety & Security			
Adaptive cruise control		Lane Departure Warning System	
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Trailer Hook / Coupling		Halogen Headlights	
HID Headlights			
 Entertainment			
Rear Seat Entertainment		Bluetooth Player	
Apple Play		Android Auto Play	
Infotainment System		USB player	
 Performance			
Differential Locks			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Dented



Front right door
Condition: Scratched



Rear left door
Condition: Scratched, Dented



Rear right door
Condition: Scratched



Fenders Condition

Left Fender



Right Fender
Right Fender: Paint Chip-off



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper
Rear Bumper: Chip < 8mm, Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
RHS Pillar B Condition	✓	Right C Pillar Trim	✓
RHS Pillar C Condition	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Left D pillar	✓		
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓

Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		

Battery

Battery Terminal & Tightness	✓		
------------------------------	---	--	--

Fuel System

Fuel Tank	✓		
-----------	---	--	--

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓
Transmission Operation	✓		

Steering, Suspension & Brakes

Steering

Steering wheel Condition: Trim Scratched	!	Shock absorbers	✓
---	---	-----------------	---

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
---------------	---	-----------------------	---

Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Suspension	✓	Shock Absorbers	✓

 **Electricals, Controls & Lights**

Keys

Master Key	✓	Spare Key(s)	✓
------------	---	--------------	---

Door Locks

Central Locking Operation	✓	Child Safety Locking	✓
---------------------------	---	----------------------	---

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Airbags

Airbags	✓		
---------	---	--	--

Controls

✓	Cruise Control	✓
---	----------------	---

Heads Up Display

✓	Infotainment Display	✓
---	----------------------	---

OBD Connector

✓	Radar (If Equipped)	✓
---	---------------------	---

Navigation System

✓	Music System	✓
---	--------------	---

Bluetooth Operations

✓

Sunroof Operation

Sunroof	✓		
---------	---	--	--

Camera

✓

Lights

Lights	✓	Running lights	✓
--------	---	----------------	---

Headlight

✓	Interior Lights	✓
---	-----------------	---

Tail Light Cluster

✓	Turn Signal Lights	✓
---	--------------------	---

Daylight Running Lights

✓	License Plate Light	✓
---	---------------------	---

Back Up Light

✓	Fog Lights	✓
---	------------	---

Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
Rear Blower Switch	✓	AC Wind Direction	✓
Rear Left AC Vent	✓		
Rear Defogger	✓	USB Charging Port	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisors	✓
Sunvisor	✓	Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	!
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim Rear Left Door: Light Scuffing	!	Door Hinge Condition	✓
Grab Handle	✓	Carpet Front floor carpet: Stained	!

Headliner

Headliner condition: Torn/Dirty



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE